

CJ WC

04/08/2013 OperationControlTicket vers. 1 CLD9 Original Page 1

<i>Order</i>	41815880	PATR/INSP 10058 DRUM-SUMMIT #2		
<i>Order type</i>	T180	EL TRANS EXPENSE RECURRING		
<i>Status</i>	REL NMAT PRC SETC			
<i>User Status</i>	UNSC			
<i>Start date</i>	07/30/2013			
<i>End date</i>	07/31/2013			
<i>FuncLocation</i>	ETL.1450.POLE.WOOD	10058 DRUM-SUMMIT #2-WOOD POLE		
<i>Equipment</i>	40582705	009/113A SINGLE WOOD POLE		
<i>MaintPlanGroup</i>	TLP	ECES		
<i>MainWrkCenter</i>	SACTO	Sacramento		
<i>Priority</i>	E	E - Schd Compl Yr 0		
<i>MaintenancePlan</i>				
<i>MaintPlanItem</i>				
<i>Revision No.</i>				
 <i>Partner</i>	ALCI	JO		
<i>Address</i>	Luz	Angie L.		12345
<i>Phone</i>	530/906-0293			
 <i>Class</i>	ETLEQP	Electric Transmission Line Equipment 002		
ETL_ACCESSIBILITY		LIGHT EQP (CREW CABS, PICKUPS)		
ETL_FRAMINGCONFIG		3 POLE SINGLE VERTICAL		
ETL_UNDERBUILT		YES		
LATITUDE		39.321025000000		
LONGITUDE		-120.621467000000		
 <i>Class</i>	ETL_POLE	002		
ETL_ACCESSIBILITY		LIGHT EQP (CREW CABS, PICKUPS)		
ETL_FRAMINGCONFIG		3 POLE SINGLE VERTICAL		
ETL_UNDERBUILT		YES		
LATITUDE		39.321025000000		
LONGITUDE		-120.621467000000		
 <i>Operation</i>	0004	Transmission OH Detailed Inspection		
<i>Work center</i>	ET_TMAN1	ECES	ELECTRIC TROUBLEMAN TRANSMISSION	
 <i>Control key</i>	INDT	<i>CompConfNo.</i>	18344559	
<i>Operation key</i>	ETL03	<i>Milestone</i>		
<i>Work</i>	12	<i>Activity type</i>	MO	
<i>Duration</i>	1	<i>Number</i>	1	
<i>EarlStartDate</i>	07/30/2013	<i>Start time</i>	00:00:00	
<i>LateEndDate</i>	07/31/2013	<i>End time</i>	00:00:00	
 <i>Actual work</i>	0	<i>Total buffer</i>	0	MIN

NAME AND LAN ID OF QCR:

BERRY WXB

SIGNATURE OF QCR:

BERRY

OF NEW TAGS GENERATED BY QCR: (2)

SIGNATURE OF SUPERVISOR: *JHR* 8/1/13

DATE

Transmission Line Inspection Datasheet

Inspector Name : BENED Date Inspection Completed : 7-31-13
Miles Inspected : 7 # Structures Inspected : 79

Order : 4181580 PATR/INSP 10058 DRUM-SUMMIT #2
 Plan Group : TLP ET Poles
 Funct Loc : ETL.1450.POLE.WOOD10058 DRUM-SUMMIT #2-WOOD POLE
 Oper Volt : 115 KV Line Miles : 28 M

 MAT Work Center : BEFZ ET_TWAN1
 ABC # Struct Order: 449 H High Impact
 ISO : Detailed Ground Inspections
 ELECTRIC TROUBLEMAN TRANSMISSION

Inspection Findings Data

Date Found	structure #	Object	Damage	Priority	Comments	Est Hrs	Clearance Yes/No/Hot	Notification #
7/16/13	27323	OF07	MEAS	E	BENT DAMPER			107062935
24/320	AEOB	CHD	F	PART SOLVED GUY WIRE				107063156

三

ט' ט' ט' ט'

8
1
3

04/08/2013 OperationControlTicket vers. 1 CLD9 Original Page 1

Order	41815880	PATR/INSP 10058 DRUM-SUMMIT #2
Order type	T180	EL TRANS EXPENSE RECURRING
Status	REL NMAT PRC SETC	
User Status	UNSC	
Start date	07/30/2013	
End date	07/31/2013	
FunctLocation	ETL.1450.POLE.WOOD	10058 DRUM-SUMMIT #2-WOOD POLE
Equipment	40582705	009/113A SINGLE WOOD POLE
MaintPlanGroup	TLP	ECES
MainWrkCenter	SACTO	Sacramento
Priority	E	E - Schd Compl Yr 0
MaintenancePlan		
MaintPlanItem		
Revision No.		

POSTED

Partner	ALCI	JO	
Address	Luz	Angie L.	
Phone	530/906-0293		12345

Class	ETLEQP	Electric Transmission Line Equipment	002
ETL_ACCESSIBILITY		LIGHT EQP (CREW CABS, PICKUPS)	
ETL_FRAMINGCONFIG		3 POLE SINGLE VERTICAL	
ETL_UNDERBUILT		YES	
LATITUDE		39.321025000000	
LONGITUDE		-120.621467000000	
Class	ETL_POLE	ETL-POLE	002
ETL_ACCESSIBILITY		LIGHT EQP (CREW CABS, PICKUPS)	
ETL_FRAMINGCONFIG		3 POLE SINGLE VERTICAL	
ETL_UNDERBUILT		YES	
LATITUDE		39.321025000000	
LONGITUDE		-120.621467000000	
Operation	0004	Transmission OH Detailed Inspection	
Work center	ET_TMAN1	ECES	ELECTRIC TROUBLEMAN TRANSMISSION

Control key	INDT	CompConfNo.	18344559
Operation key	ETL03	Milestone	
Work	12	Activity type	MO
Duration	1	Number	1
EarlStartDate	07/30/2013	Start time	00:00:00
LateEndDate	07/31/2013	End time	00:00:00
Actual work	0	Total buffer	0 MIN

COPY

NAME AND LAST OF QCR: <u>R Bimson RBBS</u>
SIGNATURE OF QCR: <u>R Bimson</u>
OF NEW TAGS GENERATED BY QCR: <u>17</u>
SIGNATURE OF SUPERVISOR: <u>JMP</u> <u>8/1/13</u>
DATE

Transmission Line Inspection Datasheet

Inspector Name : R Bimler **Date Inspection Completed :** 7-31-13
Miles Inspected : 31 **# Structures Inspected :** 253

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2
 Plan Group : TLP ET Poles
 Funct Loc : ETL.1450.POLE.WOOD10058 DRUM-SUMMIT #2-WOOD POLE
 Oper Volt : 115 KV Line Miles : 28 M

Line Last Inspected : 41619467 PATR/INSP 10058 DRUM-SUMMIT #2 (Annual Air Patrols)

07/18/2012 07/20/2012

Order : 41815880 **Patr/Insp** 10058 **Drum-Summit** #2
Plan Group : TLP **ET Poles**
Funct Loc : ETL.1450.POLE.WOOD10058 **DRUM-SUMMIT** #2-WOOD POLE
Oper Volt : 115 KV **Line Miles** : 28 M

MAT : BFZ Detailed Ground Inspections
Work Center : ET_TMAN1 ELECTRIC TROUBLEMAN TRANSMISSION
ABC : H High Impact ISO :
Struct Order : 449

Inspection Findings Data

Date	Found	structure #	object	Damage	Priority	Comments	Est Hrs	Clearance Yes/No/Hot	Notification #
7-31-13		O-6	AB10	mc02	F	Install Anchor	107062807		
7-31-13		I-14A	CF14	CH10	F	Auto Guy Splice	107062808		
7-31-13		I-14B	CF14	CH10	F	Auto Guy Splice	107062882		
7-31-13		I-14C	AG10	CH10	F	Transfer Guy's	107062883		
7-31-13		I-16	CF14	CH10	F	Auto Guy Splice	107062888		
7-31-13		I-81	CF10	CH08	F	Bolt On Connectors	107062889		
7-31-13		I-84	AB06	CH10	F	Transfer Guy's	107063157		
7-31-13		I-87	AB10	CH14	F	Replace Anchors	107063172		
7-31-13		I-102B	SW01	mc23	F	Replace Pole	107059984		
7-31-13		I-102C	SW01	mc23	F	Replace Pole	107059968		
7-31-13		I-113C	SW01	CH07	F	Replace Pole	107059980		
7-31-13		I-1509	CF14	CH10	F	Auto Guy Splices	107063155		
7-31-13		I-178C	SW01	mc23	F	Replace Pole	107059983		
7-31-13		I-201B	AB10	CH14	F	Replace Anchor	107063170		
7-31-13		I-207	IH05	mc02	F	Broken Tension	107062933		

Transmission Line Object List

Inspector Name : R.Binson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
000/001 WOOD POLE STRUCTURE 40593968 3 POLE DOUBLE VERTICAL FOOT ONLY 39.256186000000 -120.7662020000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002031	Total # of Attachments:
000/002 WOOD POLE STRUCTURE 40702390 2 POLE SUSP FOOT ONLY 39.255631000000 -120.7649720000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002032	Total # of Attachments:
000/003A SINGLE WOOD POLE 40659113 3 POLE SINGLE VERTICAL FOOT ONLY 39.255239000000 -120.7638240000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002033	Total # of Attachments:
000/003B SINGLE WOOD POLE 42572743 ANGLE 0-30 DEGREES 39.255192000000 -120.7638420000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
000/003C SINGLE WOOD POLE 42572744 ANGLE 0-30 DEGREES 39.255116000000 -120.7638770000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
000/004 WOOD POLE STRUCTURE 40771881 2 POLE SUSP FOOT ONLY 39.254983000000 -120.7625810000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002034	Total # of Attachments:
000/005 WOOD POLE STRUCTURE 40761255 3 POLE DOUBLE VERTICAL FOOT ONLY 39.254953000000 -120.7618850000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002035	Total # of Attachments:
000/006 WOOD POLE STRUCTURE 40828470 3 POLE DOUBLE VERTICAL FOOT ONLY 39.254972000000 -120.7605270000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002036	Total # of Attachments:

Install New Anchors

Transmission Line Object List

Page 2

Inspector Name : R. Bimson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments # Attachment Type/Owner Listed
000/007 WOOD POLE STRUCTURE 40826537 3 POLE DOUBLE VERTICAL FOOT ONLY 39.255006000000 -120.7598760000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002037	Total # of Attachments:
000/008 WOOD POLE STRUCTURE 40878342 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.254776000000 -120.7582460000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002038	Total # of Attachments:
000/009 WOOD POLE STRUCTURE 40862024 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.254280000000 -120.7543000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002039 <i>C.H. 31'04" VEH 75°</i>	Total # of Attachments:
000/010 WOOD POLE STRUCTURE 40590170 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.253994000000 -120.7521010000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002040	Total # of Attachments:
000/011 WOOD POLE STRUCTURE 40586191 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.253865000000 -120.7509780000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002041	Total # of Attachments:
000/012 WOOD POLE STRUCTURE 42572858 SUSPENSION (TWR) 39.253786000000 -120.7499850000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
000/013 WOOD POLE STRUCTURE 40604671 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.253535000000 -120.7487070000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002042	Total # of Attachments:
000/014A SINGLE WOOD POLE 40597040 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.253679000000 -120.7464460000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002043 <i>Auto guy splices</i>	Total # of Attachments:

Transmission Line Object List

Page 3

Inspector Name : R Bimson
Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE High Impact
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
001/014B SINGLE WOOD POLE 42572859 DOUBLE DEAD END 39.253609000000 -120.7462910000	[] completed/no problems X completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
001/014C SINGLE WOOD POLE 42572861 DOUBLE DEAD END 39.253567000000 -120.7462250000	[] completed/no problems X completed/new finding(s) X pre-existing cond chkd [] not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
001/015A SINGLE WOOD POLE 40668112 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.254499000000 -120.7456160000	X completed/no problems [] completed/new finding(s) X pre-existing cond chkd [] not inspctd this patrol Notes: '02 Survey: K002044 (CCG) LONGITUDE DATA FROM MASTER	Total # of Attachments:
001/015B SINGLE WOOD POLE 42572745 ANGLE 0-30 DEGREES 39.254474000000 -120.7455570000	[] completed/no problems [] completed/new finding(s) X pre-existing cond chkd [] not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
001/015C SINGLE WOOD POLE 42572746 ANGLE 0-30 DEGREES 39.254442000000 -120.7455180000	[] completed/no problems [] completed/new finding(s) X pre-existing cond chkd [] not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
001/016 WOOD POLE STRUCTURE 40650149 3 POLE TRAMP DOUBLE DEAD END MEDIUM EQP(AERIAL LIFT;LINE TR 39.255968000000 -120.7447270000	[] completed/no problems X completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol Notes: '02 Survey: K002046	Total # of Attachments:
001/017A SINGLE WOOD POLE 40755366 3 POLE DOUBLE VERTICAL LIGHT EQP (CREW CABS, PICKUPS) 39.257961000000 -120.7436430000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol Notes: '02 Survey: K002047	Total # of Attachments:
001/017B SINGLE WOOD POLE 42572863 DOUBLE DEAD END 39.257919000000 -120.7436650000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chkd [] not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:

Transmission Line Object List

Page 4

Inspector Name: R. Bimson
Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
001/017C SINGLE WOOD POLE 42572864 DOUBLE DEAD END 39.257955000000 -120.7435550000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
001/018 WOOD POLE STRUCTURE 40752035 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.258862000000 -120.7428690000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002048
001/019 WOOD POLE STRUCTURE 40810266 2 POLE SUSP FOOT ONLY 39.260187000000 -120.7417100000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002049
001/020 WOOD POLE STRUCTURE 40826533 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.261433000000 -120.7407690000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002050 CH 49° 10' VEH 78°
001/021 WOOD POLE STRUCTURE 40870468 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.263030000000 -120.7395560000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002051
001/022 WOOD POLE STRUCTURE 40876957 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.263507000000 -120.7391920000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002052
002/023 WOOD POLE STRUCTURE 40618800 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.264158000000 -120.7387640000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002053
002/024 WOOD POLE STRUCTURE 40594582 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.265632000000 -120.7374760000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002054

Transmission Line Object List

Page 5

Inspector Name: R BIMS D

Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
002/025 WOOD POLE STRUCTURE 40660416 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.267501000000 -120.7364400000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002055 (CCG) LONGITUDE DATA FROM MASTER
002/026 WOOD POLE STRUCTURE 40653619 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.269637000000 -120.7355880000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002056
002/027 WOOD POLE STRUCTURE 40751969 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.270124000000 -120.7354030000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002057
002/028 WOOD POLE STRUCTURE 40752037 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.270650000000 -120.7350310000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002058
002/029 WOOD POLE STRUCTURE 40810268 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.272009000000 -120.7344130000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002059
002/030A SINGLE WOOD POLE 40818745 3 POLE DOUBLE VERTICAL 39.273236000000 -120.7339190000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002060 C.H. 42' 11" U.E.H 79°
002/030B SINGLE WOOD POLE 42572865 DOUBLE DEAD END 39.273228000000 -120.7338980000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
002/030C SINGLE WOOD POLE 42572866 DOUBLE DEAD END 39.273208000000 -120.7338650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115

Transmission Line Object List

Page 6

Inspector Name : R. Bimson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
002/031 WOOD POLE STRUCTURE 40862274 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.273746000000 -120.7328140000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol Notes: '02 Survey: K002061	Total # of Attachments:
002/032 WOOD POLE STRUCTURE 40862026 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.274151000000 -120.7321350000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol Notes: '02 Survey: K002062 (CCG) LONGITUDE DATA FROM MASTER	Total # of Attachments:
002/033 WOOD POLE STRUCTURE 40603786 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.274995000000 -120.7304480000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol Notes: '02 Survey: K002063	Total # of Attachments:
003/034 WOOD POLE STRUCTURE 40590173 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.275823000000 -120.7289000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol Notes: '02 Survey: K002065 C.H. 31° V.E.H 79°	Total # of Attachments:
003/035 WOOD POLE STRUCTURE 40586192 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.276726000000 -120.7271510000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol Notes: '02 Survey: K002066	Total # of Attachments:
003/036A SINGLE WOOD POLE 40660420 3 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.277182000000 -120.7264770000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol Notes: '02 Survey: K002067	Total # of Attachments:
003/036B SINGLE WOOD POLE 42572747 ANGLE 0-30 DEGREES 39.277185000000 -120.7264510000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
003/036C SINGLE WOOD POLE 42572748 ANGLE 0-30 DEGREES 39.277154000000 -120.7263830000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol Notes: '02 Survey: K002115 C.H 41 10' V.E.H 80°	Total # of Attachments:

Transmission Line Object List

Page 7

Inspector Name : R BIMSON

Date Inspected : 7.31.13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
003/037 WOOD POLE STRUCTURE 40650152 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.278658000000 -120.7257010000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002068	Total # of Attachments:
003/038 WOOD POLE STRUCTURE 40751971 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.280047000000 -120.7250610000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002069	Total # of Attachments:
003/039A SINGLE WOOD POLE 40771048 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.281262000000 -120.7246410000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002070	Total # of Attachments:
003/039B SINGLE WOOD POLE 42572867 DOUBLE DEAD END 39.281152000000 -120.7245640000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
003/039C SINGLE WOOD POLE 42572868 DOUBLE DEAD END 39.281147000000 -120.7244880000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
003/040 WOOD POLE STRUCTURE 40828472 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.281658000000 -120.7232930000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002071	Total # of Attachments:
003/041 WOOD POLE STRUCTURE 40818175 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.282147000000 -120.7218290000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002072	Total # of Attachments:
003/042 WOOD POLE STRUCTURE 40878344 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.282894000000 -120.7200020000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002073	Total # of Attachments:

Transmission Line Object List

Page 8

Inspector Name: R Bimson
Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
003/043 WOOD POLE STRUCTURE 40869615 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.283135000000 -120.7190490000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002074
003/044 WOOD POLE STRUCTURE 40618803 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.283837000000 -120.7171150000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002075
003/045 WOOD POLE STRUCTURE 40586194 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.284153000000 -120.7160710000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002076 <i>CH. 33° VEH 80°</i>
004/046 WOOD POLE STRUCTURE 40618814 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.284577000000 -120.7150640000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002077
004/047 WOOD POLE STRUCTURE 40593969 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.285092000000 -120.7136430000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002078
004/048 WOOD POLE STRUCTURE 40702392 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.285861000000 -120.7115650000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002079 <i>CH. 34° VEH 80°</i>
004/049 WOOD POLE STRUCTURE 40669054 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.286396000000 -120.7102970000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002080
004/050A SINGLE WOOD POLE 40761541 3 POLE SINGLE VERTICAL FOOT ONLY 39.287111000000 -120.7087290000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002081

Transmission Line Object List

Page 9

Inspector Name : R Bimson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
		Notes
004/050B SINGLE WOOD POLE 42572750 ANGLE 0-30 DEGREES 39.287080000000 -120.7086980000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
004/050C SINGLE WOOD POLE 42572751 ANGLE 0-30 DEGREES 39.287038000000 -120.7086220000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
004/051 WOOD POLE STRUCTURE 40761257 2 POLE SUSP FOOT ONLY 39.288010000000 -120.7079330000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002082
004/052 WOOD POLE STRUCTURE 40828474 2 POLE SUSP FOOT ONLY 39.289473000000 -120.7068140000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002083
004/053 WOOD POLE STRUCTURE 40809757 2 POLE SUSP FOOT ONLY 39.290747000000 -120.7057170000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002084 <i>C.H. 53'0" V.E.H 85"</i>
004/054A SINGLE WOOD POLE 40878349 3 POLE SINGLE VERTICAL FOOT ONLY 39.291974000000 -120.7048690000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002085
004/054B SINGLE WOOD POLE 42572753 ANGLE 0-30 DEGREES 39.291940000000 -120.7048670000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
004/054C SINGLE WOOD POLE 42572754 ANGLE 0-30 DEGREES 39.291904000000 -120.7048180000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115

Transmission Line Object List

Page 10

Inspector Name : R Bimso
 Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE High Impact
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
004/055A SINGLE WOOD POLE 40869617 3 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.292317000000 -120.7044110000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002086	Total # of Attachments:
004/055B SINGLE WOOD POLE 42572755 ANGLE 0-30 DEGREES 39.292293000000 -120.7043530000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
004/055C SINGLE WOOD POLE 42572756 ANGLE 0-30 DEGREES 39.292261000000 -120.7042880000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
004/056 WOOD POLE STRUCTURE 40603704 2 POLE SUSP FOOT ONLY 39.292961000000 -120.7038600000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002087	Total # of Attachments:
004/057A SINGLE WOOD POLE 40586195 3 POLE DOUBLE VERTICAL FOOT ONLY 39.293639000000 -120.7033220000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002088	Total # of Attachments:
004/057B SINGLE WOOD POLE 42572869 DOUBLE DEAD END 39.293632000000 -120.7032860000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
004/057C SINGLE WOOD POLE 42572870 DOUBLE DEAD END 39.293580000000 -120.7032440000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
005/058 WOOD POLE STRUCTURE 40618806 2 POLE SUSP FOOT ONLY 39.294559000000 -120.7025220000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002089	Total # of Attachments:

Transmission Line Object List

Page 11

Inspector Name : R Bimson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
		Notes
005/059A SINGLE WOOD POLE 40586197 3 POLE DOUBLE VERTICAL 39.295608000000 -120.7017540000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002090
005/059B SINGLE WOOD POLE 42572757 ANGLE 0-30 DEGREES 39.295566000000 -120.7017390000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
005/059C SINGLE WOOD POLE 42572758 ANGLE 0-30 DEGREES 39.295565000000 -120.7016790000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
005/060 WOOD POLE STRUCTURE 40660424 2 POLE SUSP FOOT ONLY 39.296478000000 -120.7000250000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002091
005/061A SINGLE WOOD POLE 40669056 3 POLE SINGLE VERTICAL FOOT ONLY 39.297140000000 -120.6989130000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002092
005/061B SINGLE WOOD POLE 42572759 ANGLE 0-30 DEGREES 39.297094000000 -120.6988250000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
005/061C SINGLE WOOD POLE 42572760 ANGLE 0-30 DEGREES 39.297077000000 -120.6988210000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
005/062A SINGLE WOOD POLE 40761543 3 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.297987000000 -120.6982370000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002093

Transmission Line Object List

Page 12

Inspector Name : RBinson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
		Total # of Attachments:
005/062B SINGLE WOOD POLE 42572761 ANGLE 0-30 DEGREES 39.297948000000 -120.6981970000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Notes: '02 Survey: K002115
005/062C SINGLE WOOD POLE 42572762 ANGLE 0-30 DEGREES 39.297919000000 -120.6981660000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Notes: '02 Survey: K002115
005/063 WOOD POLE STRUCTURE 40771046 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.298487000000 -120.6968350000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Notes: '02 Survey: K002094 CH. 32' 02" VEH 55°
005/064 WOOD POLE STRUCTURE 40828476 TRAMP DOUBLE DEAD END MEDIUM EQP(AERIAL LIFT;LINE TR 39.299288000000 -120.6951310000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Notes: '02 Survey: K002095
005/065 WOOD POLE STRUCTURE 40806531 2 POLE SUSP FOOT ONLY 39.300096000000 -120.6935880000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Notes: '02 Survey: K002096
005/066 WOOD POLE STRUCTURE 40878351 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.300890000000 -120.6920350000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Notes: '02 Survey: K002097
005/067 WOOD POLE STRUCTURE 40869619 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.301695000000 -120.6906410000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Notes: '02 Survey: K002098
005/068 WOOD POLE STRUCTURE 40603707 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.302511000000 -120.6890660000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not insptd this patrol	Notes: '02 Survey: K002099

Transmission Line Object List

Page 13

Inspector Name: R Bimson
Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #	
		Attachment Type/Owner Listed	
006/069 WOOD POLE STRUCTURE 40584508 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.303409000000 -120.6874810000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol Notes: '02 Survey: K002100	Total # of Attachments:	
006/070 WOOD POLE STRUCTURE 40582707 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.304280000000 -120.6858550000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol Notes: '02 Survey: K002101	Total # of Attachments:	
006/071 WOOD POLE STRUCTURE 40702401 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.305065000000 -120.6843390000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol Notes: '02 Survey: K002102	Total # of Attachments:	
006/072 WOOD POLE STRUCTURE 40659114 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.305958000000 -120.6826120000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol Notes: '02 Survey: K002103	Total # of Attachments:	
006/073A SINGLE WOOD POLE 40765742 3 POLE SINGLE VERTICAL FOOT ONLY 39.306435000000 -120.6819910000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol Notes: '02 Survey: K001853	Total # of Attachments:	
006/073B SINGLE WOOD POLE 42572763 ANGLE 0-30 DEGREES 39.306405000000 -120.6819560000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol Notes: '02 Survey: K002115	Total # of Attachments:	
006/073C SINGLE WOOD POLE 42572764 ANGLE 0-30 DEGREES 39.306382000000 -120.6818830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol Notes: '02 Survey: K002115	Total # of Attachments:	
006/074 WOOD POLE STRUCTURE 40771042 2 POLE SUSP FOOT ONLY 39.306583000000 -120.6803080000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspcrd this patrol Notes: '02 Survey: K001854	Total # of Attachments:	

Transmission Line Object List

Page 14

Inspector Name: R Bimson
Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
		Notes
006/075 WOOD POLE STRUCTURE 40828478 2 POLE SUSP FOOT ONLY 39.306786000000 -120.6783650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002104	Total # of Attachments: <i>C.H. 34' 03' VEH 65'</i>
006/076 WOOD POLE STRUCTURE 40809759 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.306954000000 -120.6767880000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002105	Total # of Attachments:
006/077 WOOD POLE STRUCTURE 40870449 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.307088000000 -120.6752070000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002106	Total # of Attachments:
006/078 WOOD POLE STRUCTURE 40876959 2 POLE SUSP FOOT ONLY 39.307261000000 -120.6735050000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002107	Total # of Attachments: 1 DIST-0310456 1
006/079 WOOD POLE STRUCTURE 40618809 2 POLE SUSP FOOT ONLY 39.307390000000 -120.6717880000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002108	Total # of Attachments:
007/080 WOOD POLE STRUCTURE 40618817 2 POLE SUSP FOOT ONLY 39.307598000000 -120.6699190000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002109	Total # of Attachments:
007/081 WOOD POLE STRUCTURE 40602585 3 POLE DOUBLE VERTICAL FOOT ONLY <i>Tramp - DDE</i> 39.307757000000 -120.6681620000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002110	Total # of Attachments:
007/082 WOOD POLE STRUCTURE 40660428 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.308328000000 -120.6670000000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002111	Total # of Attachments:
		<i>Bolt on Connectors</i>
		<i>CH. 36' 11" VEH 65'</i>

Transmission Line Object List

Page 15

Inspector Name : R Binson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
007/083 WOOD POLE STRUCTURE 40669058 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.308941000000 -120.6656770000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002112	Total # of Attachments:
007/084 WOOD POLE STRUCTURE 40751973 3 POLE DOUBLE VERTICAL FOOT ONLY 39.309613000000 -120.6644130000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002113	Total # of Attachments:
007/085 WOOD POLE STRUCTURE 40755597 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.310610000000 -120.6630440000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001855	Total # of Attachments:
007/086A SINGLE WOOD POLE 40810270 3 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.311179000000 -120.6623460000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001856	Total # of Attachments:
007/086B SINGLE WOOD POLE 42572765 ANGLE 0-30 DEGREES 39.311146000000 -120.6623280000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
007/086C SINGLE WOOD POLE 42572766 ANGLE 0-30 DEGREES 39.311119000000 -120.6623070000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
007/087 WOOD POLE STRUCTURE 40818177 3 POLE DOUBLE VERTICAL FOOT ONLY 39.311753000000 -120.6607650000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001857	Total # of Attachments:
007/088 WOOD POLE STRUCTURE 40862276 2 POLE SUSP FOOT ONLY 39.312112000000 -120.6590180000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001858	Total # of Attachments:

Replace ANCHORS CH. 38' 03" VEH 70°

Transmission Line Object List

Page 16

Inspector Name : R.Bimson
Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

~~High Impact~~
~~Detailed Ground Inspections~~

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
007/085 WOOD POLE STRUCTURE 40876962 2 POLE SUSP FOOT ONLY 39.312609000000 -120.6574810000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001859	Total # of Attachments:
007/090 WOOD POLE STRUCTURE 40618811 2 POLE SUSP FOOT ONLY 39.312972000000 -120.6559970000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001860	Total # of Attachments:
008/091 WOOD POLE STRUCTURE 40603710 3 POLE DOUBLE VERTICAL 39.313392000000 -120.6545610000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001861	Total # of Attachments:
008/092 WOOD POLE STRUCTURE 40602587 3 POLE DOUBLE VERTICAL 39.313688000000 -120.6525980000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001862	Total # of Attachments:
008/093 WOOD POLE STRUCTURE 40702394 3 POLE DOUBLE VERTICAL 39.314082000000 -120.6509670000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001863	Total # of Attachments:
008/094A SINGLE WOOD POLE 40659117 3 POLE SINGLE VERTICAL 39.314326000000 -120.6497060000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001864	Total # of Attachments: C.H. 35' 08" VEH 70°
008/094B SINGLE WOOD POLE 42572767 ANGLE 0-30 DEGREES 39.314268000000 -120.6496910000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
008/094C SINGLE WOOD POLE 42572768 ANGLE 0-30 DEGREES 39.314222000000 -120.6496750000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:

Transmission Line Object List

Page 17

Inspector Name : R. Bimson
 Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
		Notes
008/095 WOOD POLE STRUCTURE 40771883 2 POLE SUSP 39.315151000000 -120.6477290000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001865
008/096 WOOD POLE STRUCTURE 40771044 2 POLE SUSP 39.316099000000 -120.6458410000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001866
008/097 WOOD POLE STRUCTURE 40828480 3 POLE DOUBLE VERTICAL LIGHT EQP (CREW CABS, PICKUPS) 39.316983000000 -120.6438350000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001867
008/098A SINGLE WOOD POLE 40826567 3 POLE SINGLE VERTICAL LIGHT EQP (CREW CABS, PICKUPS) 39.317982000000 -120.6427440000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001868
008/098B SINGLE WOOD POLE 42572769 ANGLE 0-30 DEGREES 39.317952000000 -120.6426840000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
008/098C SINGLE WOOD POLE 42572770 ANGLE 0-30 DEGREES 39.317929000000 -120.6426410000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
008/099A SINGLE WOOD POLE 40878353 3 POLE SINGLE VERTICAL FOOT ONLY 39.320368000000 -120.6416630000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001869
008/099B SINGLE WOOD POLE 42572771 ANGLE 0-30 DEGREES 39.320282000000 -120.6415930000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115

Transmission Line Object List

Page 18

Inspector Name : R Bimsan

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
008/099C SINGLE WOOD POLE 42572772 ANGLE 0-30 DEGREES 39.3202424000000 -120.6415680000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
008/100 WOOD POLE STRUCTURE 40869621 2 POLE SUSP FOOT ONLY 39.320904000000 -120.6402450000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001870	Total # of Attachments:
008/101 WOOD POLE STRUCTURE 40590176 2 POLE SUSP FOOT ONLY 39.321728000000 -120.6385570000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001871	Total # of Attachments:
009/102A SINGLE WOOD POLE 40618835 3 POLE SINGLE VERTICAL FOOT ONLY 39.322713000000 -120.6367950000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001872	Total # of Attachments:
009/102B SINGLE WOOD POLE 42572774 ANGLE 0-30 DEGREES 39.322641000000 -120.6368160000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115 <i>Replace Pole</i>	Total # of Attachments:
009/102C SINGLE WOOD POLE 42572775 ANGLE 0-30 DEGREES 39.322589000000 -120.6368010000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115 <i>Replace Pole</i>	Total # of Attachments:
009/103 LATTICE STEEL TOWER, SW 40602591 FIELD SWITCH STRUCTURE MEDIUM EQP(AERIAL LIFT;LINE TR 39.322574000000 -120.6364430000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001873	Total # of Attachments:
009/104 WOOD POLE STRUCTURE 40702425 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.322229000000 -120.6343550000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001874	Total # of Attachments:

Transmission Line Object List

Page 19

Inspector Name : R.Bimson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
		Notes
009/105 WOOD POLE STRUCTURE 40650153 3 POLE DOUBLE VERTICAL FOOT ONLY 39.321862000000 -120.6328220000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001875
009/106 WOOD POLE STRUCTURE 40771897 2 POLE SUSP FOOT ONLY 39.321503000000 -120.6307220000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001876
009/107 WOOD POLE STRUCTURE 40771050 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.321278000000 -120.6292050000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001877 C.H. 45° 11' UEW 80°
009/108A SINGLE WOOD POLE 40819358 3 POLE SINGLE VERTICAL LIGHT EQP (CREW CABS, PICKUPS) 39.321071000000 -120.6276900000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001878
009/108B SINGLE WOOD POLE 42572777 ANGLE 0-30 DEGREES 39.320976000000 -120.6277330000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
009/108C SINGLE WOOD POLE 42572778 ANGLE 0-30 DEGREES 39.320924000000 -120.6277530000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
009/109 WOOD POLE STRUCTURE 40826559 3 POLE DOUBLE VERTICAL FOOT ONLY 39.321007000000 -120.6263150000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001879
009/110 WOOD POLE STRUCTURE 40862278 2 POLE SUSP FOOT ONLY 39.320958000000 -120.6245340000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001880

Transmission Line Object List

Page 20

Inspector Name : P Bimson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
009/111 WOOD POLE STRUCTURE 40876990 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.320976000000 -120.6231850000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001881	Total # of Attachments: 1 DIST-0310456 1
009/112 WOOD POLE STRUCTURE 40618837 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.320999000000 -120.6220240000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001882	Total # of Attachments: 1 DIST-0310456 1
009/113A SINGLE WOOD POLE 40582705 3 POLE SINGLE VERTICAL LIGHT EQP (CREW CABS, PICKUPS) 39.321025000000 -120.6214670000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001883	Total # of Attachments: 1 DIST-0310456 1
009/113B SINGLE WOOD POLE 42572779 ANGLE 0-30 DEGREES 39.320993000000 -120.6214540000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments: <i>Replace Pole</i>
009/113C SINGLE WOOD POLE 42572780 ANGLE 0-30 DEGREES 39.320928000000 -120.6214330000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
009/114 WOOD POLE STRUCTURE 40681165 2 POLE SUSP FOOT ONLY 39.321041000000 -120.6209210000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001884	Total # of Attachments: 1 DIST-0310456 1
009/115 WOOD POLE STRUCTURE 40669060 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.321476000000 -120.6188260000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001885	Total # of Attachments: 1 DIST-0310456 1
010/116 WOOD POLE STRUCTURE 40603712 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.321726000000 -120.6171320000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001886	Total # of Attachments: 1 DIST-0310456 1

Transmission Line Object List

Page 21

Inspector Name: P. Binsur
Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
010/117 WOOD POLE STRUCTURE 40602617 3 POLE DOUBLE VERTICAL FOOT ONLY 39.321890000000 -120.6158820000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001887	Total # of Attachments: 1 DIST-0310456 1 <i>C.H. 32' 05" VEH 70°</i>
010/118 WOOD POLE STRUCTURE 40660433 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.322186000000 -120.6145050000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001888	Total # of Attachments: 1 DIST-0310456 1
010/119A SINGLE WOOD POLE 40650155 3 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.322581000000 -120.6130360000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001889	Total # of Attachments: 1 DIST-0310456 1
010/119B SINGLE WOOD POLE 42572782 ANGLE 0-30 DEGREES 39.322529000000 -120.6130030000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
010/119C SINGLE WOOD POLE 42572783 ANGLE 0-30 DEGREES 39.322438000000 -120.6129530000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
010/120 WOOD POLE STRUCTURE 40751975 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.323227000000 -120.6123110000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001890	Total # of Attachments: 1 DIST-0310456 1
010/121A SINGLE WOOD POLE 40752039 3 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.323819000000 -120.6118190000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001891	Total # of Attachments: 1 DIST-0310456 1 <i>C.H. 42' 02" VEH 70°</i>
010/121B SINGLE WOOD POLE 42572784 ANGLE 0-30 DEGREES 39.323812000000 -120.6118240000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:

Transmission Line Object List

Page 22

Inspector Name : RBinson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments # Attachment Type/Owner Listed
		Total # of Attachments:
010/121C SINGLE WOOD POLE 42572785 ANGLE 0-30 DEGREES 39.323748000000 -120.6117950000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments: DIST-0310456 1
010/122A SINGLE WOOD POLE 40810272 3 POLE TRAMP DOUBLE DEAD END MEDIUM EQP(AERIAL LIFT;LINE TR 39.324701000000 -120.6095360000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001892	Total # of Attachments: 1
010/122B SINGLE WOOD POLE 42572871 DOUBLE DEAD END 39.324682000000 -120.6095210000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
010/122C SINGLE WOOD POLE 42572872 DOUBLE DEAD END 39.324638000000 -120.6095170000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
010/123 WOOD POLE STRUCTURE 40809761 2 POLE SUSP FOOT ONLY 39.325416000000 -120.6075070000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001893	Total # of Attachments: 1 DIST-0310456 1
010/124 WOOD POLE STRUCTURE 40878355 2 POLE SUSP FOOT ONLY 39.325682000000 -120.6068280000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001894	Total # of Attachments: 1 DIST-0310456 1
010/125 WOOD POLE STRUCTURE 40870149 2 POLE SUSP FOOT ONLY 39.326089000000 -120.6058770000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001895	Total # of Attachments: 1 DIST-0310456 1
010/126 WOOD POLE STRUCTURE 40590179 3 POLE DOUBLE VERTICAL FOOT ONLY 39.326693000000 -120.6037900000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001896	Total # of Attachments: 1 DIST-0310456 1

Transmission Line Object List

Page 23

Inspector Name : R Bimson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #	
		Attachment Type/Owner Listed	
010/127 WOOD POLE STRUCTURE 40586198 3 POLE DOUBLE VERTICAL FOOT ONLY 39.327203000000 -120.6027500000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001897	
011/128 WOOD POLE STRUCTURE 40618840 2 POLE SUSP FOOT ONLY 39.328116000000 -120.6008830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001898	
011/129 WOOD POLE STRUCTURE 40586200 2 POLE SUSP FOOT ONLY 39.328630000000 -120.5998270000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001899	
011/130 WOOD POLE STRUCTURE 40702403 3 POLE DOUBLE VERTICAL FOOT ONLY 39.329016000000 -120.5989760000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001900	
011/131 WOOD POLE STRUCTURE 40669084 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.329899000000 -120.5969490000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001901	
011/132 WOOD POLE STRUCTURE 40761545 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.330456000000 -120.5956650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001902	
011/133 WOOD POLE STRUCTURE 40748235 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.330917000000 -120.5945930000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001903	
011/134 WOOD POLE STRUCTURE 40828482 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.331750000000 -120.5927000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001904	

Transmission Line Object List

Page 24

Inspector Name: R Bimson
Date Inspected: 7-31-13

Func Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
011/135 WOOD POLE STRUCTURE 40818179 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.332584000000 -120.5907850000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001905
011/136 WOOD POLE STRUCTURE 40870452 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.332867000000 -120.5897340000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001906
011/137A SINGLE WOOD POLE 40876971 3 POLE SINGLE VERTICAL FOOT ONLY 39.333432000000 -120.5878070000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001907
011/137B SINGLE WOOD POLE 42572786 ANGLE 0-30 DEGREES 39.333365000000 -120.5877960000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
011/137C SINGLE WOOD POLE 42572787 ANGLE 0-30 DEGREES 39.333304000000 -120.5877930000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
011/138 WOOD POLE STRUCTURE 40618843 3 POLE DOUBLE VERTICAL FOOT ONLY 39.333436000000 -120.5858910000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001908
011/138B SINGLE WOOD POLE 4223342 9.333418000000 120.5858850000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
011/138C SINGLE WOOD POLE 4223341 9.333373000000 120.5858660000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:

Transmission Line Object List

Page 25

Inspector Name : R Binson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
012/139 WOOD POLE STRUCTURE 40603715 3 POLE DOUBLE VERTICAL FOOT ONLY 39.332959000000 -120.5838330000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001909	Total # of Attachments: 1 DIST-0310456 1
012/140 WOOD POLE STRUCTURE 40593971 2 POLE SUSP FOOT ONLY 39.332778000000 -120.5817570000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001910	Total # of Attachments: 1 DIST-0310456 1
012/141 WOOD POLE STRUCTURE 40660437 2 POLE SUSP FOOT ONLY 39.332662000000 -120.5804680000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001911	Total # of Attachments: 1 DIST-0310456 1
012/142A SINGLE WOOD POLE 40650157 3 POLE SINGLE VERTICAL FOOT ONLY 39.332545000000 -120.5784530000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001912	Total # of Attachments: 1 DIST-0310456 1
012/142B SINGLE WOOD POLE 42572788 ANGLE 0-30 DEGREES 39.332532000000 -120.5784400000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
012/142C SINGLE WOOD POLE 42572789 ANGLE 0-30 DEGREES 39.332512000000 -120.5784510000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
012/143 WOOD POLE STRUCTURE 40761547 2 POLE SUSP FOOT ONLY 39.332882000000 -120.5766060000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001913	Total # of Attachments: 1 DIST-0310456 1
012/144A SINGLE WOOD POLE 40752041 3 POLE DOUBLE VERTICAL FOOT ONLY 39.333217000000 -120.5746880000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001914	Total # of Attachments: 1 DIST-0310456 1

Transmission Line Object List

Page 26

Inspector Name: R Bimson

Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
012/144B SINGLE WOOD POLE 42572790 DOUBLE DEAD END 39.333138000000 -120.5747650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
012/144C SINGLE WOOD POLE 42572791 DOUBLE DEAD END 39.333054000000 -120.5747790000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
012/145 WOOD POLE STRUCTURE 40828504 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.332224000000 -120.5735810000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001915	Total # of Attachments: 1 DIST-0310456 1
012/146 WOOD POLE STRUCTURE 42572877 SUSPENSION (TWR) 39.331636000000 -120.5727470000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
012/147A SINGLE WOOD POLE 40809763 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.331098000000 -120.5720060000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001916	Total # of Attachments: 1 DIST-0310456 1
012/147B SINGLE WOOD POLE 42572873 DOUBLE DEAD END 39.331083000000 -120.5720730000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
012/147C SINGLE WOOD POLE 42572874 DOUBLE DEAD END 39.331024000000 -120.5721080000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
012/148 WOOD POLE STRUCTURE 40878376 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.329885000000 -120.5705400000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001917	Total # of Attachments: 1 DIST-0310456 1

Transmission Line Object List

Page 27

Inspector Name : R. Binson

Date Inspected : 7-31-13

Func Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
012/149 WOOD POLE STRUCTURE 40862028 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.329147000000 -120.5694650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001918	Total # of Attachments: 1 DIST-0310456 1
013/151 WOOD POLE STRUCTURE 40603718 2 POLE SUSP FOOT ONLY 39.328200000000 -120.5681530600	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001920	Total # of Attachments: 1 DIST-0310456 1
013/152 WOOD POLE STRUCTURE 40602616 2 POLE SUSP FOOT ONLY 39.327140000000 -120.5667580000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001921	Total # of Attachments: 1 DIST-0310456 1
013/153A SINGLE WOOD POLE 40682561 3 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.326242400000 -120.5656060000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001922	Total # of Attachments: 1 DIST-0310456 1
013/153B SINGLE WOOD POLE 42572792 ANGLE 0-30 DEGREES 39.326220000000 -120.5656130000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
013/153C SINGLE WOOD POLE 42572794 ANGLE 0-30 DEGREES 39.326144000000 -120.5656600000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
013/154 WOOD POLE STRUCTURE 40659118 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.325723000000 -120.5645750000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001923	Total # of Attachments: 1 DIST-0310456 1
013/155 WOOD POLE STRUCTURE 40751977 3 POLE DOUBLE VERTICAL FOOT ONLY 39.325149000000 -120.5634940000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001924	Total # of Attachments: 1 DIST-0310456 1

Transmission Line Object List

Page 28

Inspector Name : P Bimson

Date Inspected :

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments # Attachment Type/Owner Listed
013/156 WOOD POLE STRUCTURE 40752043 2 POLE SUSP FOOT ONLY 39.32391500000 -120.5617650000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001925	Total # of Attachments: 1 DIST-0310456 1
013/157 WOOD POLE STRUCTURE 40828484 2 POLE SUSP FOOT ONLY 39.32267000000 -120.5600910000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001926	Total # of Attachments: 1 DIST-0310456 1
013/158 WOOD POLE STRUCTURE 40818181 2 POLE SUSP FOOT ONLY 39.32144200000 -120.5584420000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001927	Total # of Attachments: 1 DIST-0310456 1
013/159 WOOD POLE STRUCTURE 40878357 3 POLE DOUBLE VERTICAL FOOT ONLY 39.32021000000 -120.5568930000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001928	Total # of Attachments: 1 DIST-0310456 1
013/160 WOOD POLE STRUCTURE 40859319 3 POLE DOUBLE VERTICAL FOOT ONLY 39.31970100000 -120.5554700000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001929	Total # of Attachments: 1 DIST-0310456 1
014/161 WOOD POLE STRUCTURE 40590185 3 POLE DOUBLE VERTICAL FOOT ONLY 39.31930300000 -120.5548060000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001931	Total # of Attachments: 1 DIST-0310456 1
014/162 WOOD POLE STRUCTURE 40594885 2 POLE SUSP FOOT ONLY 39.31882700000 -120.5530030000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001932	Total # of Attachments: 1 DIST-0310456 1
014/163 WOOD POLE STRUCTURE 40660441 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.31849200000 -120.5520950000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001933	Total # of Attachments: 1 DIST-0310456 1

Transmission Line Object List

Page 29

Inspector Name : R Bimson
Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
014/164 WOOD POLE STRUCTURE 40650158 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.317982000000 -120.5509930000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001934	Total # of Attachments: 1 DIST-0310456 1
014/165A SINGLE WOOD POLE 40771885 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.317250000000 -120.5492410000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001935	Total # of Attachments: 1 DIST-0310456 1
014/165B SINGLE WOOD POLE 42572796 ANGLE 0-30 DEGREES 39.317177000000 -120.5492710000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
014/165C SINGLE WOOD POLE 42572797 ANGLE 0-30 DEGREES 39.317125000000 -120.5492930000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
014/166 WOOD POLE STRUCTURE 40752045 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.316835000000 -120.5474350000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001936	Total # of Attachments: 1 DIST-0310456 1
014/167A SINGLE WOOD POLE 40821766 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.316421000000 -120.5454960000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001937	Total # of Attachments: 1 DIST-0310456 1
014/167B SINGLE WOOD POLE 42572798 DOUBLE DEAD END 39.316368000000 -120.5455930000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
014/167C SINGLE WOOD POLE 42572799 DOUBLE DEAD END 39.316357000000 -120.5455890000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:

Transmission Line Object List

Page 30

Inspector Name : R Bimson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
014/168 WOOD POLE STRUCTURE 40809765 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.315207000000 -120.5452350000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002114	Total # of Attachments: 1 DIST-0310456 1
014/169A SINGLE WOOD POLE 40878359 ANGLE 0-30 DEGREES MEDIUM EQP(AERIAL LIFT;LINE TR 39.314458000000 -120.5449250000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments: 1 DIST-0310456 1
014/169B SINGLE WOOD POLE 42572802 ANGLE 0-30 DEGREES 39.314446000000 -120.5450090000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
014/169C SINGLE WOOD POLE 42572803 ANGLE 0-30 DEGREES 39.314407000000 -120.5450550000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
014/170A SINGLE WOOD POLE 40870151 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.313392000000 -120.5435880000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002116	Total # of Attachments: 1 DIST-0310456 1
014/170B SINGLE WOOD POLE 42572804 ANGLE 0-30 DEGREES 39.313345000000 -120.5436240000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
014/170C SINGLE WOOD POLE 42572805 ANGLE 0-30 DEGREES 39.313304000000 -120.5436490000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
014/171A SINGLE WOOD POLE 40590188 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.313081000000 -120.5415650000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002117	Total # of Attachments: 1 DIST-0310456 1

CH. 30'07" VEN

Transmission Line Object List

Page 31

Inspector Name : R Bimson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
014/171B SINGLE WOOD POLE 42572806 ANGLE 0-30 DEGREES 39.313047000000 -120.5415720000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
014/171C SINGLE WOOD POLE 42572807 ANGLE 0-30 DEGREES 39.313005000000 -120.5415870000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
014/172 WOOD POLE STRUCTURE 40589136 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.312652000000 -120.5408170000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002118	Total # of Attachments: 1 DIST-0310456 1
014/173A SINGLE WOOD POLE 40682565 ANGLE 0-30 DEGREES 39.311578000000 -120.5384710000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002119	Total # of Attachments: 1 DIST-0310456 1
014/173B SINGLE WOOD POLE 42572808 ANGLE 0-30 DEGREES 39.311529000000 -120.5384610000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
014/173C SINGLE WOOD POLE 42572809 ANGLE 0-30 DEGREES 39.311487000000 -120.5384990000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
014/174 WOOD POLE STRUCTURE 40669087 39.311010000000 -120.5380700000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002120	Total # of Attachments: 1 DIST-0310456 1
015/175 WOOD POLE STRUCTURE 40590191 2 POLE SUSP FOOT ONLY 39.310433000000 -120.5376240000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002121	Total # of Attachments: 1 DIST-0310456 1

Transmission Line Object List

Page 32

Inspector Name : R.Binson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments # Attachment Type/Owner Listed
		Total # of Attachments: 1 DIST-0310456 1
015/176 WOOD POLE STRUCTURE 40586201 3 POLE DOUBLE VERTICAL FOOT ONLY 39.309808000000 -120.5371860000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002122	Total # of Attachments: 1 DIST-0310456 1 <i>C.H. 32' 02" PED 60'</i>
015/177 WOOD POLE STRUCTURE 40660445 3 POLE DOUBLE VERTICAL FOOT ONLY 39.308755000000 -120.5359620000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002123	Total # of Attachments: 1 DIST-0310456 1
015/178A SINGLE WOOD POLE 40650161 3 POLE DOUBLE VERTICAL FOOT ONLY 39.308305000000 -120.5353820000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002124	Total # of Attachments: 1 DIST-0310456 1
015/178B SINGLE WOOD POLE 42572810 ANGLE 0-30 DEGREES 39.308299000000 -120.5354240000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments: <i>SPLIT TOP</i>
015/178C SINGLE WOOD POLE 42572811 ANGLE 0-30 DEGREES 39.308211000000 -120.5354270000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
015/179 WOOD POLE STRUCTURE 40751979 2 POLE SUSP FOOT ONLY 39.307994000000 -120.5337100000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002125	Total # of Attachments: 1 DIST-0310456 1
015/180 LATTICE STEEL TOWER 40755599 DOUBLE DEAD END FOOT ONLY 39.307621000000 -120.5316800000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002126	Total # of Attachments:
015/181 WOOD POLE STRUCTURE 40819930 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.307305000000 -120.5296730000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002127	Total # of Attachments: 1 DIST-0310456 1

Transmission Line Object List

Page 33

Inspector Name : R. Bimson

Date Inspected : 7-3-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
015/182 WOOD POLE STRUCTURE 40809767 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.307139000000 -120.5281190000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol <small>Notes: '02 Survey: K002128</small>	Total # of Attachments: 1 DIST-0310456 1 <i>C.H. 36'03" VEH 75°</i>
015/183 WOOD POLE STRUCTURE 40862280 2 POLE SUSP FOOT ONLY 39.307066000000 -120.5273820000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol <small>Notes: '02 Survey: K002129</small>	Total # of Attachments: 1 DIST-0310456 1
015/184A SINGLE WOOD POLE 40862030 3 POLE SINGLE VERTICAL FOOT ONLY 39.307076000000 -120.5256240000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol <small>Notes: '02 Survey: K002130</small>	Total # of Attachments: 1 DIST-0310456 1
015/184B SINGLE WOOD POLE 42572813 ANGLE 0-30 DEGREES 39.307049000000 -120.5256070000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol <small>Notes: '02 Survey: K002115</small>	Total # of Attachments:
015/184C SINGLE WOOD POLE 42572814 ANGLE 0-30 DEGREES 39.306983000000 -120.5256100000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol <small>Notes: '02 Survey: K002115</small>	Total # of Attachments:
015/185 WOOD POLE STRUCTURE 40608754 2 POLE SUSP FOOT ONLY 39.307218000000 -120.5249570000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol <small>Notes: '02 Survey: K002131</small>	Total # of Attachments: 1 DIST-0310456 1
015/186A SINGLE WOOD POLE 40586203 3 POLE SINGLE VERTICAL FOOT ONLY 39.307606000000 -120.5237320000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol <small>Notes: '02 Survey: K002132</small>	Total # of Attachments: 1 DIST-0310456 1
015/186B SINGLE WOOD POLE 42572815 ANGLE 0-30 DEGREES 39.307570000000 -120.5236820000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol <small>Notes: '02 Survey: K002115</small>	Total # of Attachments:

Transmission Line Object List

Page 34

Inspector Name : R Bimson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
015/186C SINGLE WOOD POLE 42572816 ANGLE 0-30 DEGREES 39.307555000000 -120.5236690000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments: DIST-0310456 1
015/187 WOOD POLE STRUCTURE 40702427 2 POLE SUSP FOOT ONLY 39.308739000000 -120.5222400000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002133	Total # of Attachments: 1 DIST-0310456 1
016/188 WOOD POLE STRUCTURE 40590194 2 POLE SUSP FOOT ONLY 39.309528000000 -120.5211260000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002134	Total # of Attachments: 1 DIST-0310456 1
016/189A SINGLE WOOD POLE 40594584 3 POLE SINGLE VERTICAL FOOT ONLY 39.309907000000 -120.5207870000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002135	Total # of Attachments:
016/189B SINGLE WOOD POLE 42572817 ANGLE 0-30 DEGREES 39.309897000000 -120.5207200000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
016/189C SINGLE WOOD POLE 42572818 ANGLE 0-30 DEGREES 39.309831000000 -120.5206820000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
016/190 WOOD POLE STRUCTURE 40660449 2 POLE SUSP FOOT ONLY 39.310513000000 -120.5204330000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002136	Total # of Attachments:
016/191 WOOD POLE STRUCTURE 40650162 3 POLE DOUBLE VERTICAL FOOT ONLY 39.311527000000 -120.5198670000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002137	Total # of Attachments:

Transmission Line Object List

Page 35

Inspector Name: R Bimson

Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments # Attachment Type/Owner Listed
016/192A SINGLE WOOD POLE 40751981 3 POLE SINGLE VERTICAL FOOT ONLY 39.312910000000 -120.5192660000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002138	Total # of Attachments:
016/192B SINGLE WOOD POLE 42572820 ANGLE 0-30 DEGREES 39.312899000000 -120.5192090000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
016/192C SINGLE WOOD POLE 42572821 ANGLE 0-30 DEGREES 39.312851000000 -120.5191580000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
016/193 WOOD POLE STRUCTURE 40755601 2 POLE SUSP FOOT ONLY 39.313781000000 -120.5178670000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002139	Total # of Attachments:
016/194A SINGLE WOOD POLE 40822544 3 POLE SINGLE VERTICAL FOOT ONLY 39.314807000000 -120.5164830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002140	Total # of Attachments:
016/194B SINGLE WOOD POLE 42572822 ANGLE 0-30 DEGREES 39.314778000000 -120.5164860000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
016/194C SINGLE WOOD POLE 42572823 ANGLE 0-30 DEGREES 39.314783000000 -120.5164810000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
016/195A SINGLE WOOD POLE 40818747 3 POLE SINGLE VERTICAL FOOT ONLY 39.315099000000 -120.5141380000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002141	Total # of Attachments:

Transmission Line Object List

Page 36

Inspector Name: R Bimson

Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
016/195B SINGLE WOOD POLE 42572824 ANGLE 0-30 DEGREES 39.315058000000 -120.5141410000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
016/195C SINGLE WOOD POLE 42572825 ANGLE 0-30 DEGREES 39.315014000000 -120.5141370000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
016/196 WOOD POLE STRUCTURE 40862282 3 POLE DOUBLE VERTICAL FOOT ONLY 39.314605000000 -120.5110900000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002142	Total # of Attachments:
016/197 WOOD POLE STRUCTURE 40856571 3 POLE DOUBLE VERTICAL FOOT ONLY 39.314184000000 -120.5088250000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002143	Total # of Attachments: 1 DIST-0310456 1
016/198 WOOD POLE STRUCTURE 40590198 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.314111000000 -120.5076010000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002144	Total # of Attachments: 1 DIST-0310456 1
016/199 WOOD POLE STRUCTURE 40586204 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.313959000000 120.5058950000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002145	Total # of Attachments: 1 DIST-0310456 1
017/200 WOOD POLE STRUCTURE 0618887 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.313902000000 120.5047030000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002146	Total # of Attachments: 1 DIST-0310456 1
17/201A SINGLE WOOD POLE 0588206 POLE SINGLE VERTICAL LIGHT EQP (CREW CABS, PICKUPS) 39.313833000000 120.5027700000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002147	Total # of Attachments: 1 DIST-0310456 1

CH- 33° 10' TED 65°

Transmission Line Object List

Page 37

Inspector Name : R Bimson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments # Attachment Type/Owner Listed
		Total # of Attachments:
017/201B SINGLE WOOD POLE 42572826 ANGLE 0-30 DEGREES 39.313781000000 -120.5027960000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> incomplete/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115 <i>Install NEW ANCOR</i>	Total # of Attachments: DIST-0310456 1
017/201C SINGLE WOOD POLE 42572827 ANGLE 0-30 DEGREES 39.313720000000 -120.5027940000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> incomplete/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
017/202 WOOD POLE STRUCTURE 40660454 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.313975000000 -120.5012080000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> incomplete/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002148	Total # of Attachments: 1 DIST-0310456 1
017/203 WOOD POLE STRUCTURE 40653621 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.314153000000 -120.4998640000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> incomplete/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002149	Total # of Attachments: 1 DIST-0310456 1
017/204 WOOD POLE STRUCTURE 40762144 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.314242000000 -120.4989720000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> incomplete/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002150	Total # of Attachments: 1 DIST-0310456 1
017/205 WOOD POLE STRUCTURE 40752047 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.314432000000 -120.4977370000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> incomplete/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002151 <i>CH. 53' 07" VERT 65°</i>	Total # of Attachments: 1 DIST-0310456 1
017/206 WOOD POLE STRUCTURE 40810274 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.314605000000 -120.4964630000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> incomplete/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002152	Total # of Attachments: 1 DIST-0310456 1
017/207 WOOD POLE STRUCTURE 40809769 3 POLE DOUBLE VERTICAL FOOT ONLY 39.314798000000 -120.4950780000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> incomplete/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002153 <i>Broken Insulator</i>	Total # of Attachments: 1 DIST-0310456 1

Transmission Line Object List

Page 38

Inspector Name : R Binson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
017/208 WOOD POLE STRUCTURE 41120242 3 POLE DOUBLE VERTICAL FOOT ONLY 39.314983000000 -120.4935040000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002154	Total # of Attachments: 1 DIST-0310456 1
017/209 WOOD POLE STRUCTURE 41120243 3 POLE DOUBLE VERTICAL FOOT ONLY 39.315088000000 -120.4924680000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002155	Total # of Attachments: 1 DIST-0310456 1
017/210 WOOD POLE STRUCTURE 40618890 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.315545000000 -120.4909810000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002156	Total # of Attachments: 1 DIST-0310456 1
017/211 WOOD POLE STRUCTURE 40586207 3 POLE DOUBLE VERTICAL FOOT ONLY 39.315896000000 -120.4898270000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001939	Total # of Attachments: 1 DIST-0310456 1
017/212 WOOD POLE STRUCTURE 40660458 2 POLE SUSP FOOT ONLY 39.316228000000 -120.4884270000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001940	Total # of Attachments: 1 DIST-0310456 1
018/213 WOOD POLE STRUCTURE 40590200 2 POLE SUSP FOOT ONLY 39.316638000000 -120.4857680000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001941	Total # of Attachments: 1 DIST-0310456 1
018/214 WOOD POLE STRUCTURE 40589137 2 POLE SUSP FOOT ONLY 39.317056000000 -120.4836720000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001942	Total # of Attachments: 1 DIST-0310456 1
018/215 WOOD POLE STRUCTURE 40682569 ANGLE 0-30 DEGREES FOOT ONLY 39.317210000000 -120.4828340000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001943	Total # of Attachments: 1 DIST-0310456 1

Transmission Line Object List

Page 39

Inspector Name : R Binson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
018/216 WOOD POLE STRUCTURE 40650165 2 POLE SUSP FOOT ONLY 39.317304000000 -120.4819600000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001944	Total # of Attachments: 1 DIST-0310456 1
018/217 WOOD POLE STRUCTURE 40751983 2 POLE SUSP FOOT ONLY 39.317452000000 -120.4807290000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001945	Total # of Attachments: 1 DIST-0310456 1
018/218 WOOD POLE STRUCTURE 40755603 2 POLE SUSP FOOT ONLY 39.317590000000 -120.4791120000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001946	Total # of Attachments: 1 DIST-0310456 1
018/219 WOOD POLE STRUCTURE 40810276 2 POLE SUSP FOOT ONLY 39.317765000000 -120.4773540000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001947	Total # of Attachments: 1 DIST-0310456 1
018/220 WOOD POLE STRUCTURE 40821579 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.317953000000 -120.4758210000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001948	Total # of Attachments: 1 DIST-0310456 1
018/221 WOOD POLE STRUCTURE 40865429 2 POLE SUSP FOOT ONLY 39.318137000000 -120.4737960000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001949	Total # of Attachments: 1 DIST-0310456 1
018/222 WOOD POLE STRUCTURE 40862032 3 POLE DOUBLE VERTICAL FOOT ONLY 39.318193000000 -120.4729540000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001950	Total # of Attachments: 1 DIST-0310456 1
018/223 WOOD POLE STRUCTURE 40590203 2 POLE SUSP FOOT ONLY 39.318621000000 -120.4709270000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001951	Total # of Attachments: 1 DIST-0310456 1

Transmission Line Object List

age 40

Inspector Name: R Binson

Date Inspected: 7-31-13

Object Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
Owner : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Caming Config Access: DST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
9/224 WOOD POLE STRUCTURE 590206 POLE TRAMP DOUBLE DEAD END GHT EQP (CREW CABS, PICKUPS) .319171000000 20.4683180000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001952
9/225A SINGLE WOOD POLE 586209 POLE SINGLE VERTICAL GHT EQP (CREW CABS, PICKUPS) .319406000000 20.4674730000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001953
9/225B SINGLE WOOD POLE 572828 GLE 0-30 DEGREES .319339000000 20.4674300000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
9/225C SINGLE WOOD POLE 572829 GLE 0-30 DEGREES .319256000000 20.4674310000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
9/226 WOOD POLE STRUCTURE 668903 POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319355000000 20.4664530000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001954 <i>C.H. 44 11° VEH 60°</i>
9/227 WOOD POLE STRUCTURE 659726 POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001955
9/228 WOOD POLE STRUCTURE 751985 POLE SUSP GHT EQP (AERIAL LIFT; LINE TR) .319329000000 20.4640470000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001956
9/229 WOOD POLE STRUCTURE 771072 POLE SUSP NOT ONLY .319265000000 20.4618750000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K001957

Transmission Line Object List

Page 41

Inspector Name : B Bimson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
019/230 WOOD POLE STRUCTURE 40819360 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.319195000000 -120.4605400000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001958	Total # of Attachments: 1 DIST-0310456 1
019/231 WOOD POLE STRUCTURE 40826541 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.319151000000 -120.4591660000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001959	Total # of Attachments: 1 DIST-0310456 1
019/232 WOOD POLE STRUCTURE 40870454 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.318912000000 -120.4579500000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001960	Total # of Attachments: 1 DIST-0310456 1
019/233 WOOD POLE STRUCTURE 40862034 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.318687000000 -120.4567170000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001961	Total # of Attachments: 1 DIST-0310456 1
019/234 WOOD POLE STRUCTURE 40590209 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.318486000000 -120.4555920000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001962	Total # of Attachments: 1 DIST-0310456 1
019/235 WOOD POLE STRUCTURE 40602593 2 POLE SUSP FOOT ONLY 39.318307000000 -120.4545650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001963	Total # of Attachments: 1 DIST-0310456 1
019/236 WOOD POLE STRUCTURE 40702429 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.318263000000 -120.4533860000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001964	Total # of Attachments: 1 DIST-0310456 1
019/237 WOOD POLE STRUCTURE 40669088 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.318053000000 -120.4513380000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001965	Total # of Attachments: 1 DIST-0310456 1

Transmission Line Object List

Page 42

Inspector Name: RBIMSON
Date Inspected: 7-31-73

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
020/238 WOOD POLE STRUCTURE 40590212 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.317928000000 -120.4494320000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001966	Total # of Attachments: 1 DIST-0310456 1
020/239A SINGLE WOOD POLE 40597041 3 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.317905000000 -120.4480680000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001967	Total # of Attachments: 1 DIST-0310456 1
020/239B SINGLE WOOD POLE 42572830 ANGLE 0-30 DEGREES 39.317827000000 -120.4480340000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
020/239C SINGLE WOOD POLE 42572831 ANGLE 0-30 DEGREES 39.317804000000 -120.4480400000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
020/240 WOOD POLE STRUCTURE 40660462 2 POLE SUSP FOOT ONLY 39.318312000000 -120.4463670000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001968	Total # of Attachments: 1 DIST-0310456 1
020/241 WOOD POLE STRUCTURE 40669062 ? POLE SUSP FOOT ONLY 39.318578000000 -120.4453360000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001969	Total # of Attachments: 1 DIST-0310456 1
020/242 WOOD POLE STRUCTURE 0751987 ? POLE SUSP FOOT ONLY 39.319227000000 -120.4432580000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001970	Total # of Attachments: 1 DIST-0310456 1
020/243A SINGLE WOOD POLE 0761259 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.319836000000 -120.4413110000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001971	Total # of Attachments: 1 DIST-0310456 1

G.H. 49° 64' U2H 75°

Transmission Line Object List

Page 43

Inspector Name: R Bimson
Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE High Impact
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2 Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
020/243B SINGLE WOOD POLE 42572832 ANGLE 0-30 DEGREES 39.319820000000 -120.4412690000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
020/243C SINGLE WOOD POLE 42572833 ANGLE 0-30 DEGREES 39.319841000000 -120.4412340000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
020/244 WOOD POLE STRUCTURE 40828486 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.320737000000 -120.4401070000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001972 <i>C-H. 40' 00 VEH 70°</i>
020/245 WOOD POLE STRUCTURE 40826543 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.321754000000 -120.4388550000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001973
020/246 WOOD POLE STRUCTURE 40878374 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.322807000000 -120.4376720000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001974
020/247A SINGLE WOOD POLE 40862036 3 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.323665000000 -120.4366650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001975
020/247B SINGLE WOOD POLE 42572835 ANGLE 0-30 DEGREES 39.323602000000 -120.4366610000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
020/247C SINGLE WOOD POLE 42572836 ANGLE 0-30 DEGREES 39.323561000000 -120.4366140000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115

Transmission Line Object List

Page 44

Inspector Name: R Bimson

Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
020/248 WOOD POLE STRUCTURE 40590215 2 POLE SUSP FOOT ONLY 39.324032000000 -120.4354710000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001976	Total # of Attachments:
021/249 WOOD POLE STRUCTURE 40595354 2 POLE SUSP FOOT ONLY 39.324507000000 -120.4340160000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001977	Total # of Attachments:
021/250 WOOD POLE STRUCTURE 40594585 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.324911000000 -120.4324470000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001978	Total # of Attachments:
021/251 WOOD POLE STRUCTURE 40660466 2 POLE SUSP FOOT ONLY 39.325610000000 -120.4308660000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001979	Total # of Attachments:
021/252 WOOD POLE STRUCTURE 40646420 2 POLE SUSP FOOT ONLY 39.326202000000 -120.4292040000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001980	Total # of Attachments:
021/253 WOOD POLE STRUCTURE 40755702 2 POLE SUSP FOOT ONLY 39.326579000000 -120.4281480000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001981	Total # of Attachments:
021/254 WOOD POLE STRUCTURE 40752048 3 POLE DOUBLE VERTICAL FOOT ONLY 39.327265000000 -120.4261590000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001982	Total # of Attachments:
021/255 WOOD POLE STRUCTURE 40828488 2 POLE SUSP FOOT ONLY 39.327411000000 -120.4246170000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001983	Total # of Attachments:

Transmission Line Object List

Page 44

Inspector Name : BERNA
 Date Inspected : 7/19/13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
020/248 WOOD POLE STRUCTURE 40590215 2 POLE SUSP FOOT ONLY 39.324032000000 -120.4354710000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001976
021/249 WOOD POLE STRUCTURE 40595354 2 POLE SUSP FOOT ONLY 39.324507000000 -120.4340160000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001977
021/250 WOOD POLE STRUCTURE 40594585 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.324911000000 -120.4324470000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001978
021/251 WOOD POLE STRUCTURE 40560466 2 POLE SUSP FOOT ONLY 39.325610000000 -120.4308660000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001979
021/252 WOOD POLE STRUCTURE 40646420 2 POLE SUSP FOOT ONLY 39.326202000000 -120.4292040000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001980
021/253 WOOD POLE STRUCTURE 40755702 2 POLE SUSP FOOT ONLY 39.326579000000 -120.4281480000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001981
021/254 WOOD POLE STRUCTURE 40752048 3 POLE DOUBLE VERTICAL FOOT ONLY 39.327265000000 -120.4261590000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001982
021/255 WOOD POLE STRUCTURE 40828488 2 POLE SUSP FOOT ONLY 39.327411000000 -120.4246170000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K001983

Transmission Line Object List

Page 45

Inspector Name : BEARD
 Date Inspected : 7-19-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE High Impact
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments # Attachment Type/Owner Listed
021/256 WOOD POLE STRUCTURE 40826565 2 POLE SUSP FOOT ONLY 39.327736000000 -120.4225950000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001984	Total # of Attachments: <i>41 @ 93°</i>
021/257 WOOD POLE STRUCTURE 40878362 2 POLE SUSP FOOT ONLY 39.327860000000 -120.4213970000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001985	Total # of Attachments: <i>31 ft @ 92°</i>
021/258 WOOD POLE STRUCTURE 40859321 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.328071000000 -120.4191550000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001986	Total # of Attachments: <i>32 @ 92°</i>
021/259 WOOD POLE STRUCTURE 40603721 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.328357000000 -120.4173740000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001987	Total # of Attachments:
021/260 WOOD POLE STRUCTURE 40602619 3 POLE DOUBLE VERTICAL LIGHT EQP (CREW CABS, PICKUPS) 39.328304000000 -120.4168280000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001988	Total # of Attachments:
022/261 WOOD POLE STRUCTURE 40603723 2 POLE SUSP FOOT ONLY 39.328416000000 -120.4159320000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001990	Total # of Attachments:
022/262 WOOD POLE STRUCTURE 40593972 2 POLE SUSP LIGHT EQP (CREW CABS, PICKUPS) 39.328448000000 -120.4138320000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001991	Total # of Attachments:
022/263 WOOD POLE STRUCTURE 40702405 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.328532000000 -120.4116880000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001992	Total # of Attachments:

Transmission Line Object List

Page 46

Inspector Name : BERRY
Date Inspected : 7-19-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
022/264 WOOD POLE STRUCTURE 40669091 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.328537000000 -120.4100690000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001993	Total # of Attachments:
022/265 WOOD POLE STRUCTURE 40771887 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.328664000000 -120.4081960000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001994	Total # of Attachments: <i>60' @ 95°</i>
022/266 WOOD POLE STRUCTURE 40771052 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.328670000000 -120.4061400000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001995	Total # of Attachments:
022/267 WOOD POLE STRUCTURE 40810278 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.328793000000 -120.4041540000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001996	Total # of Attachments: <i>41' @ 95°</i>
022/268 WOOD POLE STRUCTURE 40826547 2 POLE SUSP FOOT ONLY 39.328815000000 -120.4021300000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001997	Total # of Attachments: <i>48' @ 93°</i>
022/269 WOOD POLE STRUCTURE 40870456 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.328882000000 -120.4005200000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001998	Total # of Attachments: <i>36' @ 93°</i>
022/270 WOOD POLE STRUCTURE 40876973 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.328958000000 -120.3990860000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K001999	Total # of Attachments:
023/271 WOOD POLE STRUCTURE 40618852 2 POLE SUSP FOOT ONLY 39.328944000000 -120.3978700000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002001	Total # of Attachments:

Transmission Line Object List

Page 47

Inspector Name : BEARD

Date Inspected : 7-19-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments # Attachment Type/Owner Listed
023/272 WOOD POLE STRUCTURE 40602594 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.329022000000 -120.3964810000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002002	Total # of Attachments: <i>41' @ 93°</i>
023/273 WOOD POLE STRUCTURE 40681169 2 POLE SUSP FOOT ONLY 39.329060000000 -120.3950510000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002003	Total # of Attachments: <i>31' @ 93</i>
023/274 WOOD POLE STRUCTURE 40669064 3 POLE TRAMP DOUBLE DEAD END 39.329130000000 -120.3939570000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002004	Total # of Attachments:
023/275 WOOD POLE STRUCTURE 40751989 2 POLE SUSP FOOT ONLY 39.329125000000 -120.3924120000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002005	Total # of Attachments: <i>37' @ 93°</i>
023/276 WOOD POLE STRUCTURE 40761261 2 POLE SUSP FOOT ONLY 39.329166000000 -120.3907760000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002006	Total # of Attachments: 1 DIST-0310456 1 <i>37' @ 93</i>
023/277A SINGLE WOOD POLE 40819362 3 POLE DOUBLE VERTICAL FOOT ONLY 39.329291000000 -120.3899530000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002007	Total # of Attachments:
023/277B SINGLE WOOD POLE 42572838 ANGLE 0-30 DEGREES 39.329266000000 -120.3899760000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
023/277C SINGLE WOOD POLE 42572839 ANGLE 0-30 DEGREES 39.329213000000 -120.3899740000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments: <i>43' @ 33</i>

Transmission Line Object List

Page 48

Inspector Name : BERRY
 Date Inspected : 7-19-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments # Attachment Type/Owner Listed
023/278 WOOD POLE STRUCTURE 40826545 2 POLE SUSP FOOT ONLY 39.328800000000 -120.3884840000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002008	Total # of Attachments: <u>33'</u> <u>33</u> <u>33</u>
023/280 WOOD POLE STRUCTURE 40618849 3 POLE SINGLE VERTICAL FOOT ONLY 39.328553000000 -120.3847950000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002011	Total # of Attachments:
023/281 WOOD POLE STRUCTURE 40594587 2 POLE SUSP FOOT ONLY 39.328129000000 -120.3832720000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002012	Total # of Attachments:
023/282A SINGLE WOOD POLE 40660471 3 POLE DOUBLE VERTICAL 39.327543000000 -120.3810110000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002013	Total # of Attachments:
023/282B SINGLE WOOD POLE 42572841 ANGLE 0-30 DEGREES 39.327514000000 -120.3810980000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
023/282C SINGLE WOOD POLE 42572842 ANGLE 0-30 DEGREES 39.327501000000 -120.3811020000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
023/283A SINGLE WOOD POLE 40650166 3 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.325874000000 -120.3812490000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002014	Total # of Attachments:
023/283B SINGLE WOOD POLE 42572843 ANGLE 0-30 DEGREES 39.325875000000 -120.3811870000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:

Transmission Line Object List

Page 49

Inspector Name : BENED
 Date Inspected : 7-19-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
		Notes
023/283C SINGLE WOOD POLE 42572844 ANGLE 0-30 DEGREES 39.325882000000 -120.3812820000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
024/284 WOOD POLE STRUCTURE 40590218 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.325125000000 -120.3817100000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: <i>31 @ 92°</i>
024/285 WOOD POLE STRUCTURE 40586210 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.324265000000 -120.3822120000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002016
024/286A SINGLE WOOD POLE 40660475 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.323695000000 -120.3825750000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002017
024/286B SINGLE WOOD POLE 42572845 ANGLE 0-30 DEGREES 39.323671000000 -120.3826420000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
024/286C SINGLE WOOD POLE 42572846 ANGLE 0-30 DEGREES 39.323655000000 -120.3826940000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
024/287 WOOD POLE STRUCTURE 40650168 3 POLE DOUBLE VERTICAL FOOT ONLY 39.323007000000 -120.3824000000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K002018
024/288 WOOD POLE STRUCTURE 10908634 2 POLE SUSP FOOT ONLY 39.322625000000 -120.3816340000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: K002019

Transmission Line Object List

Page 50

Inspector Name : BENARD
 Date Inspected : 7-16-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
024/289 WOOD POLE STRUCTURE 40764780 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.321983000000 -120.3807060000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002020	Total # of Attachments: 1 DIST-0310456 1
024/290 WOOD POLE STRUCTURE 40755605 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.321054000000 -120.3789710000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002021	Total # of Attachments:
024/291A SINGLE WOOD POLE 40810280 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.320576000000 -120.3781690000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002022	Total # of Attachments: 1 CELL-UNKNOWN 1
024/291B SINGLE WOOD POLE 42572875 DOUBLE DEAD END 39.320573000000 -120.3782420000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
024/291C SINGLE WOOD POLE 42572876 DOUBLE DEAD END 39.320564000000 -120.3783040000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
024/292 WOOD POLE STRUCTURE 40818183 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.319361000000 -120.3781990000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002023	Total # of Attachments:
024/293 WOOD POLE STRUCTURE 40862284 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.318715000000 -120.3782590000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002024	Total # of Attachments:
024/294 WOOD POLE STRUCTURE 40866067 2 POLE SUSP FOOT ONLY 39.317239000000 -120.3780760000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002025	Total # of Attachments:

Transmission Line Object List

Page 51

Inspector Name : BENARD
 Date Inspected : 7-16-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE High Impact
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
024/295 WOOD POLE STRUCTURE 40590221 2 POLE SUSP FOOT ONLY 39.316557000000 -120.3779590000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002026	Total # of Attachments:
024/296A SINGLE WOOD POLE 40594971 3 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.315472000000 -120.3777350000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002157	Total # of Attachments:
024/296B SINGLE WOOD POLE 42572847 ANGLE 0-30 DEGREES 39.315420000000 -120.3777580000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
024/296C SINGLE WOOD POLE 42572848 ANGLE 0-30 DEGREES 39.315422000000 -120.3778010000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
024/297 WOOD POLE STRUCTURE 40671549 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.314560000000 -120.3764180000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002158	Total # of Attachments:
025/298 WOOD POLE STRUCTURE 40618855 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.313719000000 -120.3752140000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002159	Total # of Attachments:
025/299 WOOD POLE STRUCTURE 40590178 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.312882000000 -120.3739730000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002160	Total # of Attachments:
025/300 WOOD POLE STRUCTURE 40671553 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.312138000000 -120.3728260000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002161	Total # of Attachments:

Transmission Line Object List

Page 52

Inspector Name : Bennet

Date Inspected : 7-16-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
025/301 WOOD POLE STRUCTURE 40654849 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.311308000000 -120.3715400000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002162	Total # of Attachments:
025/302A SINGLE WOOD POLE 40756991 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.310653000000 -120.3705210000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002163	Total # of Attachments:
025/302B SINGLE WOOD POLE 42572849 ANGLE 0-30 DEGREES 39.310690000000 -120.3705410000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
025/302C SINGLE WOOD POLE 42572850 ANGLE 0-30 DEGREES 39.310531000000 -120.3705550000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
025/303 WOOD POLE STRUCTURE 40765060 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.310443000000 -120.3688980000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002164	Total # of Attachments:
025/304 WOOD POLE STRUCTURE 40815055 3 POLE TRAMP DOUBLE DEAD END MEDIUM EQP(AERIAL LIFT;LINE TR 39.310285000000 -120.3675190000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002165	Total # of Attachments:
025/305 WOOD POLE STRUCTURE 40812966 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.310196000000 -120.3660490000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002166	Total # of Attachments:
025/306 WOOD POLE STRUCTURE 40871457 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.310034000000 -120.3637370000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002167	Total # of Attachments:

Transmission Line Object List

Page 53

Inspector Name : Bennet
 Date Inspected : 7-16-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result	Attachments #
		Attachment Type/Owner Listed
025/307 WOOD POLE STRUCTURE 40869623 STEEL X ARM MEDIUM EQP(AERIAL LIFT;LINE TR 39.309917000000 -120.3619200000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002168 snow cat in winter	Total # of Attachments:
025/308 WOOD POLE STRUCTURE 40597138 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.309789000000 -120.3602080000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002169	Total # of Attachments:
025/309 WOOD POLE STRUCTURE 40590183 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.309699000000 -120.3587530000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002170	Total # of Attachments:
026/310 WOOD POLE STRUCTURE 40597141 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.309578000000 -120.3569460000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002171	Total # of Attachments:
026/311A SINGLE WOOD POLE 40590181 3 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.309558000000 -120.3554180000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002172	Total # of Attachments:
026/311B SINGLE WOOD POLE 42572851 ANGLE 0-30 DEGREES 39.309454000000 -120.3554490000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
026/311C SINGLE WOOD POLE 42572852 ANGLE 0-30 DEGREES 39.309436000000 -120.3554580000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
026/312 WOOD POLE STRUCTURE 40668907 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.309007000000 -120.3539780000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002173	Total # of Attachments:

Transmission Line Object List

Page 54

Inspector Name : BERRY

Date Inspected : 7-16-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
026/313 WOOD POLE STRUCTURE 40660176 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.30852000000 -120.3524420000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002174	Total # of Attachments:
026/314A SINGLE WOOD POLE 40756993 3 POLE SINGLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.30801900000 -120.3507330000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002175	Total # of Attachments:
026/314B SINGLE WOOD POLE 42572854 ANGLE 0-30 DEGREES 39.30798300000 -120.3506990000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
026/314C SINGLE WOOD POLE 42572855 ANGLE 0-30 DEGREES 39.30793800000 -120.3507200000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002115	Total # of Attachments:
026/315 WOOD POLE STRUCTURE 40771054 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.30821400000 -120.3488250000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002176	Total # of Attachments:
026/316 WOOD POLE STRUCTURE 40815057 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.30852000000 -120.3470350000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002177	Total # of Attachments:
026/317 WOOD POLE STRUCTURE 40809771 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.30873800000 -120.3452100000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002178	Total # of Attachments:
026/318 WOOD POLE STRUCTURE 40866626 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.30929100000 -120.3432100000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002179	Total # of Attachments:

Transmission Line Object List

Page 55

Inspector Name : BEARD
 Date Inspected : 7-16-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
026/319 WOOD POLE STRUCTURE 40864944 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.309512000000 -120.3422220000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002180	Total # of Attachments:
026/320 WOOD POLE STRUCTURE 40597145 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.309802000000 -120.3409380000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002181	Total # of Attachments:
027/321 WOOD POLE STRUCTURE 40605262 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.310389000000 -120.3397730000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002182	Total # of Attachments:
027/322 LATTICE STEEL TOWER 40590184 3 POLE DOUBLE VERTICAL MEDIUM EQP(AERIAL LIFT;LINE TR 39.310777000000 -120.3384170000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002183	Total # of Attachments:
027/323 LATTICE STEEL TOWER 40671557 DOUBLE DEAD END FOOT ONLY 39.310885000000 -120.3380830000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002184	Total # of Attachments:
027/324 WOOD POLE STRUCTURE 40659727 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.311412000000 -120.3351900000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002185	Total # of Attachments:
027/325 WOOD POLE STRUCTURE 40755704 2 POLE SUSP MEDIUM EQP(AERIAL LIFT;LINE TR 39.311787000000 -120.3336460000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002186	Total # of Attachments: 1 DIST-0310456 1
027/326A SINGLE WOOD POLE 40752050 3 POLE SINGLE VERTICAL FOOT ONLY 39.312138000000 -120.3322690000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002187	Total # of Attachments:

Transmission Line Object List

Page 56

Inspector Name : BEARD
 Date Inspected : 7-16-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
027/326B SINGLE WOOD POLE 42572856 ANGLE 0-30 DEGREES 39.312108000000 -120.3322420000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
027/326C SINGLE WOOD POLE 42572857 ANGLE 0-30 DEGREES 39.312074000000 -120.3322000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002115
027/327 WOOD POLE STRUCTURE 40820272 3 POLE DOUBLE VERTICAL 39.312772000000 -120.3318620000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002188
027/328 WOOD POLE STRUCTURE 40821391 3 POLE DOUBLE VERTICAL FOOT ONLY 39.313083000000 -120.3315930000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002189
027/329 WOOD POLE STRUCTURE 40865431 2 POLE SUSP FOOT ONLY 39.313829000000 -120.3312100000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002190
027/330 WOOD POLE STRUCTURE 40870576 3 POLE DOUBLE VERTICAL FOOT ONLY 39.314946000000 -120.3304990000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002191
027/331 WOOD POLE STRUCTURE 40597148 2 POLE SUSP FOOT ONLY 39.315844000000 -120.3298190000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002192
027/332 LATTICE STEEL TOWER SW 2 40579656 FIELD SWITCH STRUCTURE FOOT ONLY 39.316215000000 -120.3295100000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: K002027

Transmission Line Object List

Page 57.

Inspector Name : BERRY
 Date Inspected : 7-16-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE
 Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
028/333 WOOD POLE STRUCTURE 40597150 2 POLE DOUBLE DEAD END FOOT ONLY 39.317122000000 -120.3291600000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol Notes: '02 Survey: K002028	Total # of Attachments: 1 DIST-0310456 1

23/279

30' @ 92°

OK.

Notification	Notif.date	Description	Description	Equipment	Functional Loc.	Required End	Reference date
106027941	04/24/2012	DRUM-SUMMIT #2 CORRECT GROUND CLERANCE			ETL.1450	05/01/2013	04/24/2012
105178716	08/18/2010	DRUM-SUMMIT #2 000/008 REPL POLE "CTR"	000/008 WOOD POLE STRUCTURE	40878342	ETL.1450	11/30/2013	08/18/2010
105971287	03/14/2012	DRUM-SUMMIT #2 000/008 REPL POLE "LFT"	000/008 WOOD POLE STRUCTURE	40878342	ETL.1450	03/14/2014	03/14/2012
105971288	03/14/2012	DRUM-SUMMIT #2 000/008 REPL POLE "RT"	000/008 WOOD POLE STRUCTURE	40878342	ETL.1450	03/14/2014	03/14/2012
105522440	10/19/2011	DRUMM-SUMMIT #2 0/09 RPL POLE LEFT/NERC	000/009 WOOD POLE STRUCTURE	40862024	ETL.1450	12/31/2013	10/19/2011
106059226	10/19/2011	DRUMM-SUMMIT #2 0/09 RPL POLE RIGT/NERC	000/009 WOOD POLE STRUCTURE	40862024	ETL.1450	12/31/2013	10/19/2011
105994441	03/29/2012	DRUM SUMMIT #2 001/013 REPL POLE "LFT"	001/013 WOOD POLE STRUCTURE	40604671	ETL.1450	11/30/2014	03/29/2012
105247629	09/13/2010	DRUM SUMMIT #2 001/013 REPL POLE "CTR"	001/013 WOOD POLE STRUCTURE	40604671	ETL.1450	10/31/2013	09/13/2010
106059077	05/22/2012	DRUMM-SUMMIT #2 1/15a RPL POLE/NERC PROJ	001/015A SINGLE WOOD POLE	40668112	ETL.1450	12/31/2013	05/22/2012
106059163	05/22/2012	DRUMM-SUMMIT #2 1/15B RPL POLE/NERC PROJ	001/015B SINGLE WOOD POLE	42572745	ETL.1450	12/31/2013	05/22/2012
106059164	05/22/2012	DRUMM-SUMMIT #2 1/15C RPL POLE/NERC PROJ	001/015C SINGLE WOOD POLE	42572746	ETL.1450	12/31/2013	05/22/2012
106059165	05/22/2012	DRUMM-SUMMIT #2 2/32 RPL POLE LEFT/NERC	002/032 WOOD POLE STRUCTURE	40862026	ETL.1450	12/31/2013	05/22/2012
106059227	05/22/2012	DRUMM-SUMMIT #2 2/32 RPL POLE RIGHT/NERC	002/032 WOOD POLE STRUCTURE	40862026	ETL.1450	12/31/2013	05/22/2012
106059166	05/22/2012	DRUMM-SUMMIT #2 2/33 RPL POLE/ LEFT/NER	002/033 WOOD POLE STRUCTURE	40603786	ETL.1450	12/31/2013	05/22/2012
106059228	05/22/2012	DRUMM-SUMMIT #2 2/33 RPL POLE RIGH/NER	002/033 WOOD POLE STRUCTURE	40603786	ETL.1450	12/31/2013	05/22/2012
106059229	05/22/2012	DRUMM-SUMMIT #2 3/35 RPL POLE RIGH/NERC	003/035 WOOD POLE STRUCTURE	40586192	ETL.1450	12/31/2013	05/22/2012
106059167	05/22/2012	DRUMM-SUMMIT #2 3/35 RPL POLE LEFT/NERC	003/035 WOOD POLE STRUCTURE	40586192	ETL.1450	12/31/2013	05/22/2012
105385129	07/30/2011	DRUM-SUMMIT #2 003/039C REPL POLE	003/039C SINGLE WOOD POLE	42572868	ETL.1450	07/31/2013	07/30/2011
106059290	05/22/2012	DRUMM-SUMMIT #2 3/43 RPL POLE RIGH/NERC	003/043 WOOD POLE STRUCTURE	40869615	ETL.1450	12/31/2013	05/22/2012
106059169	05/22/2012	DRUM-SUMMIT #2 3/43 RPL POLE LEFT/NERC	003/043 WOOD POLE STRUCTURE	40869615	ETL.1450	12/31/2013	05/22/2012
105247662	09/10/2010	DRUM SUMMIT #2 005/059A REPL POLE	005/059A SINGLE WOOD POLE	40586197	ETL.1450	10/31/2013	09/10/2010
106025478	04/23/2012	DRUM SUMMIT #2 005/059B REPL POLE	005/059B SINGLE WOOD POLE	42572757	ETL.1450	04/30/2014	04/23/2012
106025479	04/23/2012	DRUM SUMMIT #2 005/059C REPL POLE	005/059C SINGLE WOOD POLE	42572758	ETL.1450	04/30/2014	04/23/2012
105385140	07/30/2011	DRUM-SUMMIT #2 005/061A REPL POLE	005/061A SINGLE WOOD POLE	40669056	ETL.1450	07/31/2013	07/30/2011
105385143	07/30/2011	DRUM-SUMMIT #2 005/061B REPL POLE	005/061B SINGLE WOOD POLE	42572759	ETL.1450	07/31/2013	07/30/2011
105385144	07/30/2011	DRUM-SUMMIT #2 005/061C REPL POLE	005/061C SINGLE WOOD POLE	42572760	ETL.1450	07/31/2013	07/30/2011
105178721	09/11/2010	DRUM-SUMMIT #2 005/064 REPL POLE "RT"	005/064 WOOD POLE STRUCTURE	40828476	ETL.1450	11/30/2013	09/11/2010
105971320	03/14/2012	DRUM-SUMMIT #2 005/064 REPL POLE "LFT"	005/064 WOOD POLE STRUCTURE	40828476	ETL.1450	03/14/2014	03/14/2012
105178720	09/11/2010	DRUM-SUMMIT #2 005/064 REPL POLE "CTR"	005/064 WOOD POLE STRUCTURE	40828476	ETL.1450	03/14/2014	03/14/2012
105971322	03/14/2012	DRUM-SUMMIT #2 005/065 REPL POLE "RT"	005/065 WOOD POLE STRUCTURE	40806531	ETL.1450	03/14/2014	03/14/2012
105178652	09/11/2010	DRUM-SUMMIT #2 005/065 REPL POLE "LFT"	005/065 WOOD POLE STRUCTURE	40806531	ETL.1450	11/30/2013	09/11/2010
105385147	07/30/2011	DRUM-SUMMIT #2 5/066 REPL POLE "LFT"	005/066 WOOD POLE STRUCTURE	40878351	ETL.1450	07/31/2013	07/30/2011

106024081	04/23/2012	DRUM-SUMMIT #2 5/066 REPL POLE "RT"	005/066 WOOD POLE STRUCTURE	40878351	ETL.1450	04/30/2014	04/23/2012
106059200	05/22/2012	DRUMM-SUMMIT #2 6/74 RPL POLE LEFT/NERC	006/074 WOOD POLE STRUCTURE	40771042	ETL.1450	12/31/2013	05/22/2012
106059291	05/22/2012	DRUMM-SUMMIT #2 6/74 RPL POLE RIGH/NERC	006/074 WOOD POLE STRUCTURE	40771042	ETL.1450	12/31/2013	05/22/2012
105247733	09/09/2010	DRUM SUMMIT #2 007/080 REPL POLE "LFT"	007/080 WOOD POLE STRUCTURE	40618817	ETL.1450	10/31/2013	09/09/2010
105991553	09/09/2010	DRUM SUMMIT #2 007/080 REPL POLE "RT"	007/080 WOOD POLE STRUCTURE	40618817	ETL.1450	11/30/2014	09/09/2010
105178654	09/11/2010	DRUM-SUMMIT #2 007/081 REPL POLE "LFT"	007/081 WOOD POLE STRUCTURE	40602585	ETL.1450	11/30/2013	09/11/2010
105971325	03/14/2012	DRUM-SUMMIT #2 007/081 REPL POLE "RT"	007/081 WOOD POLE STRUCTURE	40602585	ETL.1450	03/14/2014	03/14/2012
105247735	09/08/2010	DRUM SUMMIT #2 007/085 REPL POLE "LFT"	007/085 WOOD POLE STRUCTURE	40755597	ETL.1450	10/31/2013	09/08/2010
105991555	03/29/2012	DRUM SUMMIT #2 007/085 REPL POLE "RT"	007/085 WOOD POLE STRUCTURE	40755597	ETL.1450	11/30/2014	03/29/2012
105991558	03/29/2012	DRUM SUMMIT#2 007/086A REPL POLE	007/086A SINGLE WOOD POLE	40810270	ETL.1450	11/30/2014	03/29/2012
105991559	03/29/2012	DRUM SUMMIT #2 007/086B REPL POLE	007/086B SINGLE WOOD POLE	42572765	ETL.1450	11/30/2014	03/29/2012
105247736	09/09/2010	DRUM SUMMIT #2 007/086C REPL POLE	007/086C SINGLE WOOD POLE	42572766	ETL.1450	10/31/2013	09/09/2010
105971329	03/14/2012	DRUM-SUMMIT #2 007/088 REPL POLE "LFT"	007/088 WOOD POLE STRUCTURE	40862276	ETL.1450	03/14/2014	03/14/2012
105178723	09/11/2010	DRUM-SUMMIT #2 007/088 REPL POLE "RT"	007/088 WOOD POLE STRUCTURE	40862276	ETL.1450	11/30/2013	09/11/2010
105971729	03/14/2012	DRUM-SUMMIT #2 008/097 REPL POLE "LFT"	008/097 WOOD POLE STRUCTURE	40828480	ETL.1450	03/14/2014	03/14/2012
105972070	03/14/2012	DRUM-SUMMIT #2 008/097 REPL POLE "RT"	008/097 WOOD POLE STRUCTURE	40828480	ETL.1450	03/14/2014	03/14/2012
105178722	09/11/2010	DRUM-SUMMIT #2 008/097 REPL POLE "CTR"	008/097 WOOD POLE STRUCTURE	40828480	ETL.1450	11/30/2013	09/11/2010
105178655	08/07/2010	DRUM-SUMMIT #2 008/099C REPL POLE	008/099C SINGLE WOOD POLE	42572772	ETL.1450	11/30/2013	08/07/2010
105178710	08/07/2010	DRUM-SUMMIT #2 009/102A REPL POLE	009/102A SINGLE WOOD POLE	40618835	ETL.1450	11/30/2013	08/07/2010
105247737	09/09/2010	DRUM SUMMIT #2 009/109 REPL POLE "CTR"	009/109 WOOD POLE STRUCTURE	40826559	ETL.1450	10/31/2013	09/09/2010
105256795	08/04/2010	DRUM SUMMIT #2 009/109 REPL POLE "RT"	009/109 WOOD POLE STRUCTURE	40826559	ETL.1450	10/31/2013	08/04/2010
105972072	03/14/2012	DRUM SUMMIT #2 009/109 REPL POLE "LFT"	009/109 WOOD POLE STRUCTURE	40826559	ETL.1450	03/14/2014	03/14/2012
105178718	08/18/2010	DRUM-SUMMIT #2 009/111B REPL POLE	009/111 WOOD POLE STRUCTURE	40876990	ETL.1450	11/30/2013	08/18/2010
105178658	08/07/2010	DRUM-SUMMIT #2 009/111 REPL POLE	009/111 WOOD POLE STRUCTURE	40876990	ETL.1450	11/30/2013	08/07/2010
106059292	05/22/2012	DRUMM-SUMMIT #2 10/118 RPL POLE RIGH/NER	010/118 WOOD POLE STRUCTURE	40660433	ETL.1450	12/31/2013	05/22/2012
106059202	05/22/2012	DRUMM-SUMMIT #2 10/118 RPL POLE LEFT/NER	010/118 WOOD POLE STRUCTURE	40660433	ETL.1450	12/31/2013	05/22/2012
105385148	07/30/2011	DRUM-SUMMIT #2 10/121A REPL POLE	010/121A SINGLE WOOD POLE	40752039	ETL.1450	07/31/2013	07/30/2011
105385170	07/30/2011	DRUM-SUMMIT #2 10/121B REPL POLE	010/121B SINGLE WOOD POLE	42572784	ETL.1450	07/31/2013	07/30/2011
105385171	07/30/2011	DRUM-SUMMIT #2 10/121C REPL POLE	010/121C SINGLE WOOD POLE	42572785	ETL.1450	07/31/2013	07/30/2011
106024088	04/23/2012	DRUM-SUMMIT #2 10/127 REPL POLE "CTR"	010/127 WOOD POLE STRUCTURE	40586198	ETL.1450	04/30/2014	04/23/2012
106024087	04/23/2012	DRUM-SUMMIT #2 10/127 REPL POLE "LFT"	010/127 WOOD POLE STRUCTURE	40586198	ETL.1450	04/30/2014	04/23/2012
105178719	08/18/2010	DRUM-SUMMIT #2 10/127 REPL POLE "RT"	010/127 WOOD POLE STRUCTURE	40586198	ETL.1450	11/30/2013	08/18/2010
105170073	09/04/2010	DRUM-SUMMIT #2 012/140 REPL POLE "LFT"	012/140 WOOD POLE STRUCTURE	40593971	ETL.1450	11/30/2013	09/04/2010

106760546	09/04/2010	DRUM-SUMMIT #2 012/140 REPL POLE "RT"	012/140 WOOD POLE STRUCTURE	40593971	ETL.1450	11/30/2013	09/04/2010
106059204	05/22/2012	DRUML-SUMMIT #2 13/152 RPL POLE LEFT/NER	013/152 WOOD POLE STRUCTURE	40602616	ETL.1450	12/31/2013	05/22/2012
106059293	05/22/2012	DRUML-SUMMIT #2 13/152 RPL POLE RIGH/NER	013/152 WOOD POLE STRUCTURE	40602616	ETL.1450	12/31/2013	05/22/2012
106025621	04/23/2012	DRUM SUMMIT #2 13/153A REPL POLE	013/153A SINGLE WOOD POLE	40682561	ETL.1450	04/30/2014	04/23/2012
105247753	08/30/2010	DRUM SUMMIT #2 13/153B REPL POLE	013/153B SINGLE WOOD POLE	42572792	ETL.1450	10/31/2013	08/30/2010
106025564	04/13/2012	DRUM-SUMMIT #2 013/156 REPL POLE "RT"	013/156 WOOD POLE STRUCTURE	40752043	ETL.1450	11/30/2013	04/13/2012
105178713	08/07/2010	DRUM-SUMMIT #2 013/156 REPL POLE "LFT"	013/156 WOOD POLE STRUCTURE	40752043	ETL.1450	11/30/2013	08/07/2010
106025568	04/23/2012	DRUM-SUMMIT #2 013/160 REPL POLE "CTR"	013/160 WOOD POLE STRUCTURE	40859319	ETL.1450	04/30/2014	04/23/2012
105178714	08/28/2010	DRUM-SUMMIT #2 013/160 REPL POLE "LFT"	013/160 WOOD POLE STRUCTURE	40859319	ETL.1450	11/30/2013	08/28/2010
106025565	04/23/2012	DRUM-SUMMIT #2 013/160 REPL POLE "RT"	013/160 WOOD POLE STRUCTURE	40859319	ETL.1450	11/30/2013	08/28/2010
105991607	03/29/2012	DRUM SUMMIT #2 14/161 REPL POLE "RT"	014/161 WOOD POLE STRUCTURE	40590185	ETL.1450	11/30/2014	03/29/2012
105991606	03/29/2012	DRUM SUMMIT #2 14/161 REPL POLE "LFT"	014/161 WOOD POLE STRUCTURE	40590185	ETL.1450	11/30/2014	03/29/2012
105247770	09/01/2010	DRUM SUMMIT #2 14/161 REPL POLE "CTR"	014/161 WOOD POLE STRUCTURE	40590185	ETL.1450	10/31/2013	09/01/2010
105991660	03/29/2012	DRUM-SUMMIT #2 014/163 REPL POLE "CTR"	014/163 WOOD POLE STRUCTURE	40660441	ETL.1450	11/30/2014	03/29/2012
105178712	08/07/2010	DRUM-SUMMIT #2 014/163 REPL POLE "LFT"	014/163 WOOD POLE STRUCTURE	40660441	ETL.1450	11/30/2013	08/07/2010
105991609	03/29/2012	DRUM SUMMIT #2 014/163 REPL POLE "RT"	014/163 WOOD POLE STRUCTURE	40590185	ETL.1450	11/30/2014	03/29/2012
106059205	05/22/2012	DRUML-SUMMIT #2 014/163 REPL POLE/NERC PRO	014/165A SINGLE WOOD POLE	40771885	ETL.1450	12/31/2013	05/22/2012
106059206	05/22/2012	DRUML-SUMMIT #2 014/165BRPL POLE/NERC PRO	014/165B SINGLE WOOD POLE	42572796	ETL.1450	12/31/2013	05/22/2012
106059208	05/22/2012	DRUML-SUMMIT #2 014/165CRPL POLE/NERC PRO	014/165C SINGLE WOOD POLE	40660441	ETL.1450	11/30/2014	03/29/2012
106059210	05/22/2012	DRUML-SUMMIT #2 014/167ARPL POLE/NERC PRO	014/167A SINGLE WOOD POLE	40821766	ETL.1450	12/31/2013	05/22/2012
106059211	05/22/2012	DRUML-SUMMIT #2 014/167BRPL POLE/NERC PRO	014/167B SINGLE WOOD POLE	42572798	ETL.1450	12/31/2013	05/22/2012
106059212	05/22/2012	DRUML-SUMMIT #2 014/167CRPL POLE/NERC PRO	014/167C SINGLE WOOD POLE	42572799	ETL.1450	12/31/2013	05/22/2012
106059214	05/22/2012	DRUML-SUMMIT #2 014/170ARPL POLE/NERC PRO	014/170A SINGLE WOOD POLE	40870151	ETL.1450	12/31/2013	05/22/2012
106059215	05/22/2012	DRUML-SUMMIT #2 014/170BRPL POLE/NERC PRO	014/170B SINGLE WOOD POLE	42572804	ETL.1450	12/31/2013	05/22/2012
106059216	05/22/2012	DRUML-SUMMIT #2 014/170CRPL POLE/NERC PRO	014/170C SINGLE WOOD POLE	42572805	ETL.1450	12/31/2013	05/22/2012
106059217	05/22/2012	DRUML-SUMMIT #2 015/184ARPL POLE/NERC PRO	015/184A SINGLE WOOD POLE	40862030	ETL.1450	12/31/2013	05/22/2012
106059218	05/22/2012	DRUML-SUMMIT #2 015/184BRPL POLE/NERC PRO	015/184B SINGLE WOOD POLE	42572813	ETL.1450	12/31/2013	05/22/2012
106059219	05/22/2012	DRUML-SUMMIT #2 015/184CRPL POLE/NERC PRO	015/184C SINGLE WOOD POLE	42572814	ETL.1450	12/31/2013	05/22/2012
106059294	05/22/2012	DRUML-SUMMIT #2 015/185RPL POLE/RIGH/NER	015/185 WOOD POLE STRUCTURE	40608754	ETL.1450	12/31/2013	05/22/2012
106059220	05/22/2012	DRUML-SUMMIT #2 015/185RPL POLE/LEFT/NER	015/185 WOOD POLE STRUCTURE	40608754	ETL.1450	12/31/2013	05/22/2012
105247755	08/21/2010	DRUM SUMMIT #2 15/186A REPL POLE	015/186A SINGLE WOOD POLE	40586203	ETL.1450	10/31/2013	08/21/2010
105178715	08/21/2010	DRUM-SUMMIT #2 015/187 REPL POLE "RT"	015/187 WOOD POLE STRUCTURE	40702427	ETL.1450	11/30/2013	08/21/2010
105991664	03/29/2012	DRUM-SUMMIT #2 015/187 REPL POLE "LFT"	015/187 WOOD POLE STRUCTURE	40702427	ETL.1450	11/30/2014	03/29/2012
106059221	05/22/2012	DRUML-SUMMIT #2 16/198 RPL POLE LEFT/NER	016/198 WOOD POLE STRUCTURE	40590198	ETL.1450	12/31/2013	05/22/2012

106059295	05/22/2012	DRUMM-SUMMIT #2 16/198 RPL POLE RIGH/NER	016/198 WOOD POLE STRUCTURE	40590198	ETL.1450.	12/31/2013	05/22/2012
106025593	04/23/2012	DRUM-SUMMIT #2 018/218 REPL POLE "RT"	018/218 WOOD POLE STRUCTURE	40755503	ETL.1450.	04/30/2014	04/23/2012
105178656	08/21/2010	DRUM-SUMMIT #2 018/218 REPL POLE "LFT"	018/218 WOOD POLE STRUCTURE	40755603	ETL.1450.	11/30/2013	08/21/2010
106059296	05/22/2012	DRUMM-SUMMIT #2 18/220 RPL POLE RIGH/NER	018/220 WOOD POLE STRUCTURE	40821579	ETL.1450.	12/31/2013	05/22/2012
106059222	05/22/2012	DRUMM-SUMMIT #2 18/220 RPL POLE LEFT/NER	018/220 WOOD POLE STRUCTURE	40821579	ETL.1450.	12/31/2013	05/22/2012
106025595	04/23/2012	DRUM-SUMMIT #2 018/221 REPL POLE "LFT"	018/221 WOOD POLE STRUCTURE	40865429	ETL.1450.	04/30/2014	04/23/2012
105178657	08/21/2010	DRUM-SUMMIT #2 018/221 REPL POLE "LFT"	018/221 WOOD POLE STRUCTURE	40865429	ETL.1450.	11/30/2013	08/21/2010
106024089	04/23/2012	DRUM-SUMMIT #2 19/230 REPL POLE "LFT"	019/230 WOOD POLE STRUCTURE	40819360	ETL.1450.	04/30/2014	04/23/2012
105178717	08/18/2010	DRUM-SUMMIT #2 019/230 REPL POLE "RT"	019/230 WOOD POLE STRUCTURE	40819360	ETL.1450.	11/30/2013	08/18/2010
105401965	07/30/2011	DRUM SUMMIT#2 020/239B REPL POLE	020/239B SINGLE WOOD POLE	42572830	ETL.1450.	07/31/2013	07/30/2011
105401966	07/30/2011	DRUM SUMMIT#2 020/239C REPL POLE	020/239C SINGLE WOOD POLE	42572831	ETL.1450.	07/31/2013	07/30/2011
106059297	05/22/2012	DRUMM-SUMMIT #2 22/265 RPL POLE RIGH/NER	022/265 WOOD POLE STRUCTURE	40771887	ETL.1450.	12/31/2013	05/22/2012
106059223	05/22/2012	DRUMM-SUMMIT #2 22/265 RPL POLELEFT/NER	022/265 WOOD POLE STRUCTURE	40771887	ETL.1450.	12/31/2013	05/22/2012
105178711	08/07/2010	DRUM-SUMMIT #2 025/309 REPL POLE "LFT"	025/309 WOOD POLE STRUCTURE	40590183	ETL.1450.	11/30/2013	08/07/2010
106025475	04/23/2012	DRUM-SUMMIT #2 025/309 REPL POLE "RT"	025/309 WOOD POLE STRUCTURE	40590183	ETL.1450.	04/30/2014	04/23/2012
106059298	05/22/2012	DRUMM-SUMMIT #2 26/316 RPL POLE RIGH/NER	026/316 WOOD POLE STRUCTURE	40815057	ETL.1450.	12/31/2013	05/22/2012
106059224	05/22/2012	DRUMM-SUMMIT #2 26/316 RPL POLE LEFT/NER	026/316 WOOD POLE STRUCTURE	40815057	ETL.1450.	12/31/2013	05/22/2012